PUBLIC HEARING BOARD OF HOUSING QUALITY APPEALS CITY HALL McCLOSKEY CONFERENCE ROOM July 13, 2011

4:00 P.M.

I.	ROLL C	ALL						
II.	REVIEW OFSUMMARY (to be emailed on Monday, July 11, 2011)							
III. OLD BUSINESS								
	(1)	11-TV-42 620 & 622 N. Adams Street , Clifton Bell. Request for an extension of time to complete repairs. Previously heard on April 13, 2011. pp. 4-12						
IV.	NEW BL	JSINESS .						
	(2)	11-TV-87 525-527 S. Village Court , L&M Rentals. Request for an extension of time to complete repairs. pp. 13-25						
	(3)	11-TV-88 729 S. Washington Street , Jacqueline & Dan Willens. Request for an extension of time to complete repairs. pp. 26-36						
	(4)	11-AA-89 806 S. Chambers Avenue , Joanne Sabbagh. Request for relief from an administrative decision. pp. 37-39						
	(5)	11-TV-90 1114 S. Nancy Street , Elizabeth Grant Investments. Request for an extension of time to complete repairs. pp. 40-46						
	(6)	11-V-91 1407 N. Woodburn Avenue , Jacqueline Cushman. Request for modification or exception to the Property Maintenance Code. pp. 47-51						
	(7)	11-V-92 2511 N. Kinser Pike , Douglas & Cameron Davis and Felicia Tiritilli. Request for modification or exception to the PMC. pp. 52-56						
	(8)	11-TV-93 1214-1216 N. Grant Street, CS Property Mgt. Request for an extension of time to complete repairs. pp. 57-64						
	(9)	11-TV-94 512 W. Dixie Street , Elaine Apple Trust c/o Old National. Request for an extension of time to complete repairs. pp. 65-85						
	(10)	11-TV-95 516 S. Jordan Avenue , Laurence Ayres. Request for an extension of time to complete repairs. pp. 86-91						
	(11)	11-TV-96 500 E. Graham Place , Parker Real Estate Mgt. Request for an extension of time to complete repairs. pp. 92-97						
	(12)	11-TV-97 507 E. Graham Place , Parker Real Estate Mgt. Request for an extension of time to complete repairs. pp. 98-103						
	(13)	11-TV-98 1736 N. Lincoln Street , Parker Real Estate Mgt. Request for an extension of time to complete repairs. pp. 104-109						
	(14)	11-TV-99 511 N. Fess Avenue , Long Real Estate Investments L.P. Request for an extension of time to complete repairs. pp. 110-125						

- (15) 11-TV-100 1033 E. Maxwell Lane, William Coulter. Request for an extension of time to complete repairs. pp. 126-131
- (16) 11-TV-101 1014 N. Jackson Street, Adam & Debra Holden. Request for an extension of time to complete repairs. pp. 132-136
- (17) 11-TV-102 **514 W. 6th Street**, Stasny & Horn IGP. Request for an extension of time to complete repairs. pp. 137-142
- V. GENERAL DISCUSSION
- VI. PUBLIC COMMENT
- VII. ADJOURNMENT

BOARD OF HOUSING QUALITY APPEALS CONSENT AGENDA CITY HALL McCLOSKEY CONFERENCE ROOM July 13, 2011, 4:00 P.M.

l.	State Variance							
	(2)	11-TV-87 525-527 S. Village Court , L&M Rentals. Request for an extension of time to complete repairs. pp. 13-25						
	(11)	11-TV-96 500 E. Graham Place , Parker Real Estate Mgt. Request for an extension of time to complete repairs. pp. 92-97						
	(12)	11-TV-97 507 E. Graham Place , Parker Real Estate Mgt. Request for an extension of time to complete repairs. pp. 98-103						
	(13)	11-TV-98 1736 N. Lincoln Street , Parker Real Estate Mgt. Request for an extension of time to complete repairs. pp. 104-109						
II.	Extension	of time to complete repairs						
	(3)	11-TV-88 729 S. Washington Street , Jacqueline & Dan Willens. Request for an extension of time to complete repairs. pp. 26-36						
	(5)	11-TV-90 1114 S. Nancy Street , Elizabeth Grant Investments. Request for an extension of time to complete repairs. pp. 40-46						
	(8)	11-TV-93 1214-1216 N. Grant Street , CS Property Mgt. Request for an extension of time to complete repairs. pp. 57-64						
	(9)	11-TV-94 512 W. Dixie Street , Elaine Apple Trust c/o Old National. Request for an extension of time to complete repairs. pp. 65-85						
	(10)	11-TV-95 516 S. Jordan Avenue , Laurence Ayres. Request for an extension of time to complete repairs. pp. 86-91						
	(14)	11-TV-99 511 N. Fess Avenue , Long Real Estate Investments L.P. Request for an extension of time to complete repairs. pp. 110-125						
	(15)	11-TV-100 1033 E. Maxwell Lane , William Coulter. Request for an extension of time to complete repairs. pp. 126-131						
	(16)	11-TV-101 1014 N. Jackson Street , Adam & Debra Holden. Request for an extension of time to complete repairs. pp. 132-136						
	(17)	11-TV-102 514 W. 6th Street , Stasny & Horn IGP. Request for an extension of time to complete repairs. pp. 137-142						



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-42 (old business)

Address:

620 & 622 N Adams

Petitioner:

Clifton Bell

Inspector:

John Hewett

Staff Report:

October 26, 2010

Completed Cycle Inspection

November 10, 2011

Sent Report

February 15, 2011

Sent RV

February 22, 2011

Received Appeal

April 13, 2011

BHQA granted Extension

The Petitioner is requesting additional time to make repairs. Weather has still been an issue and he is doing the work on his own.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline:

July 27, 2011 for all smoke detectors, fire extinguishers and

electrical violations; August 14, 2011 for all other violations

Attachments:

Cycle Inspection Reports, Petitioner's letters



Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420

Petitioner's Name: Clifon Bell
Petitioner's Address & Phone Number: 703 W. Temperance, Ellettsville I
Owner's Name: Clifton Bell
Owner's Address & Phone Number: Same - 812-360-2836
Address of Property: 620 and 622 N. adams.
Occupant(s) Name(s):
 The following conditions must be found in each case in order for the Board to consider the request: That the value of the area about the property to which the exception is to apply will not be adversely affected. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety, and general welfare.
Identify the variance type that you are requesting from the following list and attach the required information. A. An extension of time to complete repairs. (Petition type: TV) Specify the items that need the extension of time to complete Explain why the extension is needed Specify the time requested B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V) Specify the code reference number you are appealing Detail why you are requesting the variance Specify the modifications and or alterations you are suggesting C. Relief from an administration decision. (Petition type: AA) Specify the decision being appealed and the relief you are seeking D. Rescind a variance. (Petition type: RV) Detail the existing variance Specify the reason the variance is no longer needed
I certify that all information submitted with this request is correct and I have enclosed the \$20.00 filing fee.
Signature: (Will be assigned by BHQA) I - T V - 4 2 (old) Petition Number:

(Please use the reverse side for further explanation and/or request)



Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420

(Please write a brief narrative in the space provided below. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting.)


Clifon Bell	needs	another	30 da	145
+ 0 complet				0
Still been a				
help is go			·	
0				
				· .
	•			
	,			
				,
Signature: Off B		Date:	5-17-11	



Application for Appeal To The

Board of Housing Quality Appeals

P.O. Box 100 Bloomington, IN 47402 812-349-3420



Petitioner's Name: Petitioner's Address & Phone Number: RMDerar Owner's Address & Phone Number: Address of Property: () 20 000 The following conditions must be found in each case in order for the Board to consider the request: That the value of the area about the property to which the exception is to apply will not be adversely affected. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety, and general welfare. Identify the variance type that you are requesting from the following list and attach the required information. An extension of time to complete repairs. (Petition type: TV) Specify the items that need the extension of time to complete Explain why the extension is needed ☐ Specify the time requested B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V) Specify the code reference number you are appealing Detail why you are requesting the variance Specify the modifications and or alterations you are suggesting C. Relief from an administration decision. (Petition type: AA) Specify the decision being appealed and the relief you are seeking D. Rescind a variance. (Petition type: RV) L+ Detail the existing variance Specify the reason the variance is no longer needed I certify that all information submitted with this request is correct and I have enclosed the \$20.00 filing fee. Signature: Petition Number

(Please use the reverse side for further explanation and/or request).

2



Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420

'lease write a brief narrative in the space provided below. Be specific as to what you are requesting, the reason(s) or stification(s) for your request, the amount of time needed to bring the property into compliance, as well as any odifications and/or alterations you are suggesting.)

Clifen Bell	meeds	120	days t	υ
Complete re		•		
death ic			• • •	
weather	•			
				· · · · · · · · · · · · · · · · · · ·
	•			
	٠			
			Ţ.	
ASS BOD	1-ρ	Dates	9/22	/1/
Signatures MS Bef	1	Date:	2/22	



City of Bloomington Housing and Neighborhood Development

Cycle Report

998

1,30%

OWNERS

BELL, CLIFTON R. & PATRICIA A. 703 W. TEMPERANCE ELLETTSVILLE, IN 47429

Prop. Location: 620 N ADAMS ST Date Inspected: 10/26/2010 Inspectors: John Hewett Primary Heat Source: Gas Property Zoning: RC

Number of Stories: 1

Number of Units/Structures: 1 / 1

Number of Bedrooms: 1 Max # of Occupants: 2

Foundation Type: Crawl Space

Attic Access: Yes Accessory Structure:

Interior

Living room

13-3 x 13-2

Provide a complete directory of all service panels and circuits. PM-605.1

SE bedroom

13-7 x 11-4

Install a smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

Existing Egress Window Measurements:

Height: 36 inches Width: 12 inches Sill Height: 19 inches Openable Area: 3 sq. ft.

At the time this structure was built, there were no code requirements for emergency egress for a sleeping room. The Housing & Neighborhood Development Department strongly recommends that the sleeping room egress windows be modified or replaced with a larger window to aid in emergency escape. BMC-16.04.040 (b)

Furnace closet

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Rental Inspections: (812) 349-3420

Neighborhood Division: (812) 349-3421

Housing Division: (812) 349-3401

www.bloomington.in.gov

City Hall

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

Kitchen

11-4 x 12-2

Replace the torn floor covering. PM-304.4

NW room

 $9-4 \times 6-7$

No violations noted.

Bathroom

No violations noted.

Exterior

Install an approved closing device for the front storm door. PM-303.15

Install a junction box at the wire splice above the back door. PM-605.1

Repair the chipped and broken concrete on the front porch and steps. PM-303.10

Paint the exposed bare wood of the ceiling on the front porch. PM-303.2

Repair the holes in the porch roof framing. PM-303.10

Other requirements

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



City of Bloomington Housing and Neighborhood Development

Cycle Report

12

OWNERS

BELL, CLIFTON R. & PATRICIA A. 703 W. TEMPERANCE ELLETTSVILLE, IN 47429

Prop. Location: 622 N ADAMS ST

Date Inspected: 10/26/2010 Inspectors: John Hewett

Primary Heat Source: Gas

Property Zoning: RC Number of Stories: 1 Number of Units/Structures: 1/1 Number of Bedrooms: 1 approved

Max # of Occupants: 2

Foundation Type: Crawl Space

Attic Access: Yes
Accessory Structure:

Interior

Kitchen

11-1 x 12-5

A minimum 1A 10BC classification fire extinguisher shall be mounted in a visible, accessible location, in or adjacent to the kitchen, away from the range, and in the path of egress. The securing mechanism must be no more than 5 feet above the floor. PM-704.3.

Living room

11-4 x 13-11

No violations noted.

Bedroom

9-0 x 11-4

Install the door trim on the inside of the door casing. PM-304.1

Existing Egress Window Measurements:

Height: 23 inches Width: 27 inches Sill Height: 27 inches Openable Area: 4.3 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Bathroom

Repair the sink faucet to have hot water and to be free of leaks. PM-504.1



401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582 City Hall

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421 Housing Division: (812) 349-3401

www.bloomington.in.gov

Back Hall

Replace the missing protective cover for the light fixture. PM-605.1

Exterior

Repair the handrail on the back porch steps. PM-303.12

Repair the roof on the back porch. These repairs shall use materials and methods designed for use on a flat roof. PM- 303.7

Properly secure the loose fascia boards on the front (west side) of the house. PM-303.9

Repair the broken front porch stair handrail. PM-303.12

This violation has a one-year deadline from the date of the Cycle Inspection (10/26/2010). Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2

Other requirements

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied, BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-87

Address:

525-527 Village Ct.

Petitioner:

L&M Rentals

Inspector:

Robert Hoole

Staff Report:

April 7, 2011

Cycle inspection report mailed

May 12, 2011

Appeal filed

May 24, 2011

Reinspection conducted

June 9, 2011

Remaining violations report mailed

The petitioner is requesting an extension of time to secure an egress variance from the State of Indiana. No mention was made of other repairs, including life-safety issues.

Staff recommendation:

Grant the extension of time to secure an egress variance. No

extension is granted for other items

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline:

Securing an egress variance:

August 13, 2011

All other items:

Immediately


Attachments:

Appeal form, cycle inspection report, remaining violations report



Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100

Bloomington, IN 47402 812-349-3420



Petitioner's Name:	BY:
Petitioner's Address & Phone Number: 8210 Add & De	322873
Owner's Name: Mattlew Astle	
Owner's Address & Phone Number:	
Address of Property: 525-520 0//he 6	1
Occupant(s) Name(s):	
The following conditions must be found in each case in order for the Board to consider to the That the value of the area about the property to which the exception is to apply will not be 2. That the exception is consistent with the intent and purpose of the housing code and promisafety, and general welfare.	e adversely affected.
A. An extension of time to complete repairs. (Petition type: TV) Specify the items that need the extension of time to complete Explain why the extension is needed Specify the time requested B. A modification or exception to the Housing Property Maintenance Code. (P Specify the code reference number you are appealing Detail why you are requesting the variance Specify the modifications and or alterations you are suggesting C. Relief from an administration decision. (Petition type: AA) Specify the decision being appealed and the relief you are seeking D. Rescind a variance. (Petition type: RV) Detail the existing variance Specify the reason the variance is no longer needed	
I certify that all information submitted with this request is correct and I have enclosed the	
HI-T	igned by BHQA) V-87
Name (print): /// / / / / / / Petition Number:	

(Please use the reverse side for further explanation and/or request)



Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420

(Please write a brief narrative in the space provided below. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting.)

Remaining Violations Report Reinspected 5/24/2011

3793

OWNERS

----CASCIO, MATTHEW V.
8318 ASHLEY AVENUE
BLOOMINGTON, IN 47401

AGENT
=====
L&M RENTALS
8318 ASHLEY AVENUE
BLOOMINGTON IN 47401

Prop. Location: 525-527 S VILLAGE CT
Date Inspected: 03/30/2011
Inspectors: Robert Hoole
Primary Heat Source: Gas
Property Zoning: PUD
Number of Stories: 2

Number of Units/Structures: 2 / 1 Number of Bedrooms: 3 Max # of Occupants: 3 Foundation Type: Slab Attic Access: Yes Accessory Structure:

REINSPECTION REQUIRED

This report is your final notice from the Housing and Neighborhood Development Office that this rental property continues to be in violation of the Housing-Property Maintenance Code of Bloomington.

If you have made all of the repairs on this report, contact our office immediately to schedule the required re-inspection.

Failure to make repairs or to schedule the required re-inspection will result in this matter being referred to the City Legal Department. Legal action may be initiated against you under Section 16.12.100 of the Bloomington Municipal Code.

It is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection. Our mailing address and telephone number are listed below.

INTERIOR

527

Utility room

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

Properly align and secure the flue connection to the top of the water heater. PM-603.2

1st floor inner bedroom

Existing Egress Window Measurements:

Height:

44 inches

Width:

26 inches

Sill Height:

36 inches

Openable Area: 7.94 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements. Removable sashes.

1st floor outer bedroom

Existing Egress Window Measurements:

Height:

44 inches

Width:

26 inches

Sill Height:

36 inches

Openable Area: 7.94 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements. Removable sashes.

2nd floor bedroom / bath

Clean and service the exhaust fan so that it functions as intended. PM-603.1

The emergency egress window does not meet the minimum requirements for a one and two family dwelling built in 1993:

Openable area required: 4.75 sq. ft. Existing area: 6.75 sq. ft. Clear width required: 18" Existing width: 27" Existing height: 36" Maximum sill height: 44" above finished floor Existing sill: 49"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

525

<u>Utility room</u>

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level: 0 parts per million (ppm)

Acceptable level in a living space: 9 ppm Maximum concentration for flue products: 50 ppm

PM-603.1

2nd floor bedroom / bath

The emergency egress window does not meet the minimum requirements for a one and two family dwelling built in 1993:

Openable area required: 4.75 sq. ft. Existing area: 6.75 sq. ft. Clear width required: 18" Existing width: 27" Existing height: 36" Maximum sill height: 44" above finished floor Existing sill: 49"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is

altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

OTHER REQUIREMENTS:

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)

Cycle Report

3793

OWNERS

CASCIO, MATTHEW V. 8318 ASHLEY AVENUE BLOOMINGTON, IN 47401

AGENT

L&M RENTALS 8318 ASHLEY AVENUE BLOOMINGTON IN 47401

Prop. Location: 525-527 S VILLAGE CT

Date Inspected: 03/30/2011 Inspectors: Robert Hoole Primary Heat Source: Gas Property Zoning: PUD Number of Stories: 2 Number of Units/Structures: 2 / 1

Number of Bedrooms: 3 Max # of Occupants: 3 Foundation Type: Slab Attic Access: Yes Accessory Structure:

NOTE: Room inventory and dimensions are on file. Only those areas containing violations are listed in this report.

INTERIOR

527

Kitchen

A minimum 1A 10BC classification fire extinguisher shall be mounted in a visible, accessible location, in or adjacent to the kitchen, away from the range, **and in the path of egress**. The securing mechanism must be no more than 5 feet above the floor. PM-704.3.

All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. PM-704.3

Utility room

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

Properly align and secure the flue connection to the top of the water heater. PM-603.2

Eliminate the water leak near the inlet connection of the water heater, PM-504.1

Temperature/pressure relief (TPR) valve discharge tubes:

- shall not be reduced in size from the valve outlet
- shall be rigid galvanized, rigid copper, or any CPVC pipe
- shall not have a threaded discharge end
- drain by gravity
- shall have a minimum 1" air gap where discharging into a sanitary drain, or an approved air
- shall extend to within 6" of floor, PM-505.4

1st floor inner bedroom

Existing Egress Window Measurements:

Height:

44 inches

Width:

26 inches

Sill Height:

36 inches

Openable Area: 7.94 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements. Removable sashes.

1st floor outer bedroom

Existing Egress Window Measurements:

Height:

44 inches

Width:

26 inches

Sill Height:

36 inches

Openable Area: 7.94 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements. Removable sashes.

2nd floor bedroom / bath

Clean and service the exhaust fan so that it functions as intended. PM-603.1

The emergency egress window does not meet the minimum requirements for a one and two family dwelling built in 1993:

Openable area required: 4.75 sq. ft. Existing area: 6.75 sq. ft. Clear width required: 18" Existing width: 27" Existing height: 36" Maximum sill height: 44" above finished floor Existing sill: 49"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

Attached garage

Repair the vehicle door to lock as intended. PM-303.15

525

Kitchen

A minimum 1A 10BC classification fire extinguisher shall be mounted in a visible, accessible location, in or adjacent to the kitchen, away from the range, **and in the path of egress**. The securing mechanism must be no more than 5 feet above the floor. PM-704.3.

All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. PM-704.3

Utility room

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

Eliminate all water leaks from the water heater, PM-504.1

1st floor hallway

Replace the missing hard-wired smoke detector. PM-704.1

1st floor inner bedroom

Existing Egress Window Measurements:

Height:

44 inches

Width:

26 inches

Sill Height:

36 inches

Openable Area: 7.94 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements. Removable sashes.

1st floor outer bedroom

Existing Egress Window Measurements:

Height:

44 inches

Width:

Sill Height:

26 inches 36 inches

Openable Area: 7.94 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements. Removable sashes.

2nd floor bedroom / bath

Clean and service the exhaust fan so that it functions as intended. PM-603.1

The emergency egress window does not meet the minimum requirements for a one and two family dwelling built in 1993:

Openable area required: 4.75 sq. ft. Existing area: 6.75 sq. ft. Clear width required: 18" Existing width: 27" Existing height: 36" Maximum sill height: 44" above finished floor Existing sill: 49"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

EXTERIOR

Replace the missing dryer exhaust termination fitting for unit 527. PM-303.6

OTHER REQUIREMENTS

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of

the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-88

Address:

729 S. Washington Street

Petitioner:

Dan Willens

Inspector:

Jo Stong

Staff Report:

May 6, 2011: Conducted cycle inspection

May 13, 2011: Sent report May 26, 2011: Received appeal

During a cycle inspection several violations of the Property Maintenance Code were noted. The petitioner is requesting an extension of time to complete repairs.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the possibility of fines.

Compliance Deadline:

July 27, 2011 for all smoke detector and fire extinguisher

violations. September 13, 2011 for all other violations.

Attachments:

Cycle Report, Photos, Application for appeal





BY: Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

Property Address: 729 S. Washingt	on St.		
Petitioner's Name: Dan Willens	- 11		
Address: 7245 Noel Rd.			
City: Indianapolis	State: Indiana	Zip Code: 46278	
Phone Number: (317) 388-1111	E-mail Address: wilco-dan@comcast.net		
Owner's Name: Jackie willens			
Address: 1655 N. Hartstrait Rd.			
City: Bloomington	State: Indiana	Zip Code: 47404	
Phone Number: 317-388-1111	E-mail Address: none		
Occupants: tmoreno660@gmail.co	m; benfichter@gmail.com		
1. That the exception is consistent health, safety, and general welfa	with the intent and purpos are.	der for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely	
Identify the variance type that	you are requesting from t	he following drop down menu:	
Variance Type: An extension of tir	ne to complete repairs. (Petitio	on Type: TV)	
Reminder: A \$20.00 filing fee must be submi Application or the application wil complete! A completed application prior to the meeting application of placed on that months agenda!	I not be considered to be on has to be submitted	(Will be assigned by BHQA) //- TV- 88 Petition Number:	

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

country un	til June 13th, l	my mother, Jac out will be retur ete the repairs I to	ning to	Bloomington t	nen. She	has requeste	d that I	request	an extension
l am	therefore	requesting	the	maximum	time	possible	for	the	extension.
Thank		you	l,		[Dan			Willens

Signature (Required):			
Name (Print): Dan Willens	Date:	5/25/11	

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



Cycle Report

825

OWNERS

WILLENS, JACQUELINE 1655 N. HARTSTRAIT RD. BLOOMINGTON, IN 47404

Prop. Location: 729 S WASHINGTON ST

Date Inspected: 05/06/2011

Inspectors: Jo Stong

Primary Heat Source: Gas Property Zoning: RC

Number of Stories: 1

Number of Units/Structures: 1 / 1

Number of Bedrooms: 3 Max # of Occupants: 4 Foundation Type: Basement

Attic Access: No

Accessory Structure: Garage

Monroe County Assessor's records indicate this structure was built in 1925. There were no requirements for emergency egress at the time of construction.

INTERIOR:

Note: Room dimensions are in the file and are not included in this report.

Living Room:

Install a smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

Repair windows to be capable of being easily opened and held in position by their own hardware. PM-303.13.2

Provide a cover for the window air conditioner. PM-603.1

Properly install the window air conditioner in a workmanlike manner, in accordance with the manufacturer's instructions. PM-304.3, PM-102.5

29

401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582 City Hall

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421 Housing Division: (812) 349-3401

Southwest Bedroom:

Repair the south window to latch securely. PM-303.13.2

Scrape and paint windows where paint is peeling or wood is exposed. PM-304.3

Southwest Bedroom (cont'd):

Existing Egress Window Measurements (double-hung):

Height: 24 inches Width: 28 inches Sill Height: 22 inches Openable Area: 4.66 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Kitchen:

All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. PM-704.3

Southeast Bedroom:

Note: A door leading directly to the exterior serves as the emergency egress for this sleeping room.

Install a smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

Scrape and paint window where paint is peeling or wood is exposed. PM-304.3

BASEMENT (entrance in floor of southeast bedroom)

The basement was not accessible at the time of inspection. The basement must be inspected and brought into compliance within the same 60 day deadline as the remainder of this property. PM-104.4

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level: 0 parts per million (ppm)

Acceptable level in a living space: 9 ppm

Maximum concentration for flue products: 50 ppm PM-603.1

Laundry Area:

Repair the entry door to be weather tight. No gaps shall be visible around the edges. PM-303.13

Repair or replace the broken back door. PM-303.15

Northwest Bedroom:

Note: A door leading directly to the exterior serves as the emergency egress for this sleeping room.

Repair windows to be capable of being easily opened and held in position by their own hardware. PM-303.13.2

Scrape and paint windows where paint is peeling or wood is exposed. PM-304.3

Replace the missing electrical receptacle cover plate on the south wall. PM-605.1

Bathroom:

Properly repair floor in a workmanlike manner. This includes but is not limited to replacing or repairing damaged or deteriorated floor covering, decking and structural members. PM-304.2, PM-304.4, PM-102.5

Replace the rotting tub surround in a workmanlike manner. PM-304.3, PM-504.3, PM-102.5

EXTERIOR:

Properly tuck-point all missing or defective mortar joints in the foundation walls. PM-302.7 & PM-303.10

Repair the eave and fascia over the front and back doors. PM-303.6, PM-303.7

Repair the torn screen in the south window. PM-303.13

Repair the broken window on the south side (east corner). PM-303.13

Replace the missing siding on the southeast corner. PM-303.1

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. PM-302.4.1

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (this violation has a one-year deadline from the date of the cycle inspection)

Garage:

Repair all broken windows. PM-303.13

Remove trees growing at the foundation of the garage. All trees on premises shall be in good health and pose no danger to persons or building. PM-302.4.1

Remove and properly dispose of all trash and debris on property. PM-302.1

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (this violation has a one-year deadline from the date of the cycle inspection)

OTHER REQUIREMENTS:

Required documentation:

A completed copy of the Tenants & Owners Rights and Responsibilities Summary must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied.BMC16.12.050 (d).

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)

Thank you for your cooperation in the Residential Rental Occupancy Permit Program.



















Board of Housing Quality Appeals Staff Report: Petition for Relief from an Administrative Decision

Meeting Date:

July 13, 2011

Petition Type:

Relief from an administrative decision

Variance Request:

Relief from the requirement to register as a rental

Petition Number:

11-AA-89

Address:

806 Chambers

Petitioner:

Joanne Sabbagh

Ms. Sabbagh contacted us to say that her son lives in this property and requested that it be removed from the rental registration & inspection program. CBU shows water is in the name of William Sabbagh and usage indicates one person residing there.

Staff recommendation:

Grant the relief from the rental registration process

Conditions: This agreement shall remain in force so long as Mr. William Sabbagh resides in the property with no more than one other person. This property will be pull dated for 2014 to check residency.

Compliance Deadline: None

Attachments: Appeal form, letter from petitioner



Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

Property Address: 806 Chambers I	Orive	
Petitioner's Name: Joanne Sabbag	h	
Address: 3709 Tamarron Drive		
City: Bloomington	State: Indiana	Zip Code: 47408
Phone Number: 812-336-2026	E-mail Address: jsabbag	h@homefinder.org
Owner's Name: Joanne Sabbagh		
Address: Same as above		
City:	State:	Zip Code:
Phone Number:	E-mail Address:	
Occupants: William E. Sabbagh		
1. That the exception is consistent whealth, safety, and general welfar	with the intent and purpos e.	der for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely
Identify the variance type that y	ou are requesting from t	he following drop down menu:
Variance Type: A modification of ex	ception to the Housing Prop	erty Maintenance Code. (Petition Type: 🔌 🏄
Reminder: A \$20.00 filing fee must be submitted Application or the application will complete! A completed application prior to the meeting application deplaced on that months agenda!	not be considered to be n has to be submitted	(Will be assigned by BHQA) $11 - AA - 89$ Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

			. 1

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-90

Address:

1114 S. Nancy

Petitioner:

Elizabeth Grant

Inspector:

Robert Hoole

Staff Report:

April 7, 2011

Cycle inspection report mailed

June 2, 2011

Appeal filed

The petitioner is requesting an extension of time to complete repairs, citing weather as the reason repairs have not been completed in a timely fashion.

Staff recommendation:

Grant the extension of time for repairs other than replacing the fire

extinguisher.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline:

Replacement of discharged fire extinguisher: Immediately

Items other than roof and fire extinguisher:


August 13, 2011

Roof repair:

September 13, 2011

Attachments:

Appeal form, cycle inspection report



Page 1 of 2

R	Y-	
u	6 0	

Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420

hand@bloomington.in.gov

<u>.</u>	
Property Address: /// 4 S. Nanc	y, Bloomington On
Petitioner's Name: E/12abeth Gran	1+ 1140
Address: 815 Church Camp	Road
	▼ Zip Code: 474a/
Phone Number: 812-275 4249 E-mail Address: eq	ung@ hotmail.com
Owner's Name:	ove)
Address:	
City: 4 State: "	▼ Zip Code: "
Phone Number: E-mail Address:	alove)
Occupants: Os Obone	
 The following conditions must be found in each case in ore That the exception is consistent with the intent and purpos health, safety, and general welfare. 	control of the contro
That the value of the area about the property to which the affected.	exception is to apply will not be adversely
Identify the variance type that you are requesting from t	he following drop down menu:
Variance Type: (x tension) to make	e the Tew resame
Danlera	
Reminder: A \$20.00 filing fee must be submitted with the Appeal	(Will be assigned by BHQA)
Application or the application will not be considered to be	(h
complete! A completed application has to be submitted	11-71-90
prior to the meeting application deadline in order to be placed on that months agenda!	Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

Please grant me an adatetional
tom & woolete the year
upans noted: I intend to
Deroof the house. Too, it
B. Wh Isant we could
not gaint and then have et
not flesh white the
dy sufficiently

Signature (Requi	ired): Walet Grant	
Name (Print):	Elizabeth Grant	Date: 39 May 11
Important infor	mation regarding this application format:	, / /

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form

Cycle Report

4843

OWNERS ===== GRANT, ELIZABETH A. 875 CHURCH CAMP RD. BEDFORD, IN 47421

Prop. Location: 1114 S NANCY ST Date Inspected: 03/23/2011 Inspectors: Robert Hoole Primary Heat Source: Gas Property Zoning: RS Number of Stories: 1 Number of Units/Structures: 1 / 1 Number of Bedrooms: 2 Max # of Occupants: 3 Foundation Type: Crawl Space Attic Access: Yes Accessory Structure:

INTERIOR

Living room (19 x 13)

Show documentation that the fireplace has been inspected within the last twelve months, or permanently and visibly seal the fireplace to prevent its use. Service and inspection shall include the firebox, damper, chimney and/or flue. Cleaning by a professional service is highly recommended. PM-603.1

Repair the entry door to be weather tight. PM-303.15

Hallway

No violations noted.

Bath

Eliminate the drip from the sink faucet. PM-504.1

Front bedroom $(9 \frac{1}{2} \times 10)$

Existing Egress Window Measurements:

Height: 22 inches
Width: 31 inches
Sill Height: 27 inches

Openable Area: 4.73 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Rear bedroom (10 x 13)

Existing Egress Window Measurements:

Height: 22 inches
Width: 31 inches
Sill Height: 27 inches
Openable Area: 4.73 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Dining room (11 x 10)

No violations noted.

Kitchen (9 x 8)

Replace the discharged fire extinguisher. A minimum 1A 10BC classification fire extinguisher shall be mounted in a visible, accessible location, in or adjacent to the kitchen, away from the range, and in the path of egress. The securing mechanism must be no more than 5 feet above the floor. PM-704.3.

All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. PM-704.3 NOTE: The fire extinguisher was located in an adjacent room. There is a door separating the two rooms. Relocate the fire extinguisher in the kitchen so that there is no door separating it from the kitchen.

Utility room

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

Provide a complete directory of all service panels and circuits. PM-605.1

Reconnect the dryer exhaust duct to the dryer. PM-403.5

Attached garage

No violations noted.

Attic

No violations noted.

Crawlspace

No access

EXTERIOR

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 NOTE: This item has a compliance deadline of 3/23/2012.

Replace the rotted trim on the garage. PM-303.6

Properly repair the garage roof. The tenant reports that the roof leaks and there are water stains visible on the interior wall of the garage. PM-303.7

OTHER REQUIREMENTS

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Variance

Meeting Date:

13 July 2011

Petition Type:

A modification or exception to the Property Maintenance Code

Variance Request:

Pass through access to a bedroom

Petition Number:

11-V-091

Address:

1407 N. Woodburn Ave.

Petitioner:

Jacqueline Cushman

Inspector:

Michael Arnold

Staff Report:

08 April 2011 Cycle Inspection 20 April 2011 Sent Inspection Report 03 June 2011 Reinspection Scheduled Received Appeal Application 06 June 2011 13 June 2011 Reinspection cancelled 14 June 2011 Reinspection scheduled Reinspection rescheduled 21 June 2011

During the cycle inspection it was noted that there was a pass-thru issue with the west bedroom. The west bedroom is accessible only through the bathroom or through the northwest room. The Property Maintenance Code states in Sec. 404.4.2, "Bedrooms shall not constitute the only means of access to other bedrooms or habitable spaces and shall not serve as the only means of egress from other habitable areas".

Staff recommendation: Grant the variance

Conditions:

None

Compliance Deadline: None

Attachments: Application, Inspection report

Page 1 of 2





BY: _____Application For Appeal
To The
Board of Housing Quality Appeals
P.O. Box 100
Bloomington, IN 47402
812-349-3420
hand@bloomington.in.gov

Property Address:	1407 N Woedburn Ave	, Bloomington, IN 97404
Petitioner's Name:	Jacqueline Cushman	
Address: Cull	ently same as above /	Will have new address soon
City:	State:	Zip Code:
Phone Number: 910	1-327-0341 E-mail Address:	lacqueline. Cushman () Indiana. od
	same as above	
Address:		
City:	State:	Zip Code:
Phone Number:	E-mail Address:	
Occupants: Av	gust 1,2011	
1. That the exception health, safety, and	is consistent with the intent and pur general welfare.	order for the Board to consider the request: pose of the housing code and promotes public the exception is to apply will not be adversely
Identify the varianc	e type that you are requesting fro	m the following drop down menu:
Variance Type:	エ	
Application or the apcomplete! A complete	ust be submitted with the Appeal plication will not be considered to be ed application has to be submitted application deadline in order to be as agenda!	(Will be assigned by BHQA) $11-V-91$ Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - Specify the reason the variance is no longer needed.

I am petitioning to have this home classified as a three bedroom, rather than a two bedroom. There are three bedrooms - each with goodsized Windows and closets and Square tootage. The buch bedroom is not currently classified as a bedsoom because one must enter/exit through the bathroom or one of the bedrooms. Since is has two reasonable exits, plus three windows, I'd like it to be considered a three-bearoom home. Thank you for your consideration.

Name (Print): Jacqueline Cushman Date: 6/3/11	Signature (Req	uired):			
name (Finit): Jacqve1124 (USN/Mari Date: 6/3/11	Name (Print):	Jacqueline	Cushman	Date:	6/3/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Cycle Report

9548

OWNERS

CUSHMAN, JACQUELINE 1407 N. WOODBURN AVENUE BLOOMINGTON, IN 47404

AGENT

=====

BLOOMINGTON RENTALS, INC. P.O. BOX 1327 BLOOMINGTON IN 47402

Prop. Location: 1407 N WOODBURN AVE

Date Inspected: 04/08/2011 Inspectors: Mike Arnold Primary Heat Source: Gas

Property Zoning: RS

Number of Stories: 1

Number of Units/Structures: 1 / 1

Number of Bedrooms: 2 Max # of Occupants: 3 Foundation Type: Basement

Attic Access: No

Accessory Structure: garage

Interior:

Basement:

Install a smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

Main Level:

Living Room (25-11 x 13-4):

Every window shall be capable of being easily opened and held in position by its own hardware. PM-303.13.2

Kitchen, Bathroom, Screened Porch, Garage:

No violations noted

NW Room (1-5 x 10-0):

This room is not approved for sleeping purposes. PM-404.4.2

SW Bedroom (1-6 x 12-6):

Existing Egress Window Measurements:

Height:

23 inches

Width:

27 inches

Sill Height: 28 inches

Openable Area: 4.3sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

No violations noted

West Bedroom (17-9 x 15-9):

Existing Egress Window Measurements:

Height: 33 inches
Width: 35 inches
Sill Height: 37 inches
Openable Area: 8.1 sq. ft.

Note: These measurements are for reference only. There is no violation of

the emergency egress requirements.

No violations noted

Exterior:

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. PM-302.4.1

Required Documentation:

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level: 0 parts per million (ppm)

Acceptable level in a living space: 9 ppm Maximum concentration for flue products: 50 ppm

PM-603.1

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Variance

Meeting Date:

13 July 2011

Petition Type:

A modification or exception to the Property Maintenance Code

Variance Request:

Exception to PM-303.13.2 Openable Windows

Petition Number:

11-V-092

Address:

2511 N. Kinser Pk.

Petitioner:

Douglas H. Davis and Felicia Tiritilli-Davis

Inspector:

Michael Arnold

Staff Report:

09 March 2011

Cycle complete with resident

23 March 2011

Sent Inspection Report

23 May 2011

Received Appeal application

25 May 2011

Reinspection complete with resident

During the cycle inspection it was noted that several of the windows in the Family Room/Sun Room did not open as intended. The crank mechanisms do no function or are missing on several of the windows. The code states, "Every window, other than a fixed window, shall be easily openable and capable of being held in position by window hardware. All openable windows shall have fixed secure locking mechanisms".

Staff recommendation: Deny the variance

Conditions:

All windows in the Family Room/Sun Room (NW Room) shall function

as intended.

Compliance Deadline: 13 September 2011

Attachments:

Application, Cycle Inpsection



Application For Appeal To The Board of Housing Quality Appeal P.O. Box 100 Bloomington, IN 47402



BY:

hand@bloomington.in.go	hand@bl	looming	jton.in	.go
------------------------	---------	---------	---------	-----

Property Address	s: 2511 N. Kinser P	ike, Bloomington, IN 47404	
Petitioner's Nam	e: Douglas H. Dav	is and Felicia Tiritilli-Davis	1
Address: 2085 Lak	ke Run Dr.		
City: Greenwood		State: Indiana	Zip Code: 46143
Phone Number:	(317) 919-2321	E-mail Address: ftd1@sb	cglobal.net
Owner's Name:	Douglas H. Davis, I	Felicia Tiritilli-Davis, Cameron 🏻	Davis
Address: 2085 Lak	ke Run Dr.		
City: Greenwood		State: Indiana	Zip Code: 46143
Phone Number:	317-919-2321	E-mail Address: ftd1@sb	cglobal.net
Occupants: Came	eron Davis, Alex W	atkins, Johnathan Seitz	
1. That the except health, safety, a	ion is consistent nd general welfa	with the intent and purposite.	ler for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely
Identify the vari	ance type that	you are requesting from t	he following drop down menu:
Variance Type:	A modification or e	exception to the Housing Propo	erty Maintenance Code. (Petition Type: V)
Application or the complete! A com	e application will pleted application ing application o	tted with the Appeal I not be considered to be on has to be submitted Jeadline in order to be	(Will be assigned by BHQA) $//-\sqrt{-92}$ Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

We are seeking an exception to PM303.13.2 Openable windows. This is in regard to the windows in what has been described as a family room on the cycle inspection report for a Rental Occupancy Permit of March 23, 2011. This room is actually an add-on sunroom, which is an extension of the living/dining area. It is completely open to those areas by a six-foot wide open doorway, and has ventilation by virtue of the back door, front door, living room window and the two openable windows in the room itself. The residence also has central air-conditioning.

This sunroom has nine jalousie windows that completely cover the three exterior walls (on the north, west and south sides of the room), with three windows on each wall. Also on the west wall is the back door to the residence, which has a screen door. Two of the nine windows, on different walls, are operable. The fact that these windows do not open does not pose any hazard to the occupants of the residence, as they are neither a method of egress nor a necessary source of

We have contacted window contractors who have informed us that repairing these windows is not advisable due to the fact that this type of window is obsolete, the needed parts are not easily obtainable and the work required, which goes beyond simply trying to repair the crank handles that operate the windows, would be extensive to the point of being financially unfeasible. When we purchased the residence in June, 2009, this was the condition of these windows and, to the best of our knowledge, this was also the case at the time the last Rental Occupancy Permit was issued on April 30, 2008. The residence is in good repair, safe and suitable for comfortable occupancy, and these windows do not detract from that, nor do they adversely affect the value of the property in the area, and so we are requesting this exception.

Signature (Required): Death of Flicia apritule Selis

Name (Print): Douglas H. Davis

Felicia Tiritilli-Davis

Date:

5/18/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form

Cycle Report

8681

OWNERS

=====

DAVIS, CAMERON 2085 LAKE RUN DRIVE GREENWOOD, IN 46143 DAVIS, DOUGLAS 2085 LAKE RUN DRIVE GREENWOOD, IN 4641

Prop. Location: 2511 N KINSER PIKE

Date Inspected: 03/09/2011 Inspectors: Mike Arnold Primary Heat Source: Gas Property Zoning: RS Number of Stories: 1 Number of Units/Structures: 1 / 1 Number of Bedrooms: 4

Max # of Occupants: 3
Foundation Type: Basement

Attic Access: Yes

Accessory Structure: shed

Interior:

Lower Level:

Bedroom (24-5 x 13-0):

Existing Egress Window Measurements:

Height: 31 inches
Width: 28 inches
Sill Height: 43.5 inches
Openable Area: 6.03 sq. ft.

Note: These measurements are for reference only. There is no violation of

the emergency egress requirements.

No violations noted

Bathroom, Utility Room, garage:

No violations noted

Upper Level:

Living Room (16-6 x 14-8), Kitchen (9-0 x 8-3), Dining Room (12-0 x 11-0), Bathroom:

No violations noted

Family Room $(17-0 \times 12-0)$:

Repair the window cranks to function as intended. PM-303.12.2

NE Bedroom (10-0 x 9-0), SE Bedroom (11-0 x 9-0):

Existing Egress Window Measurements:

Height: 31 inches
Width: 28 inches
Sill Height: 43.5 inches
Openable Area: 6.03 sq. ft.

Note: These measurements are for reference only. There is no violation of

the emergency egress requirements.

No violations noted

SW Bedroom (13-1 x 11-1):

Existing Egress Window Measurements:

Height: 31 inches
Width: 28 inches
Sill Height: 43.5 inches
Openable Area: 6.03 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Replace the missing hardwired interconnected smoke detector. PM-704.1

Exterior:

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (Front porch posts, foundation on the west side of the structure and anywhere else that paint is peeling or cracking).

Repair/replace the damaged screen on the storm door. PM-303.15

Required Documentation:

A completed copy of the Tenants & Owners Rights and Responsibilities Summary must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied.BMC16.12.050 (d).

A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-93

Address:

1214 & 1216 N. Grant Street

Petitioner:

CS Property Management

Inspector:

Maria McCormick

Staff Report:

April 11, 2011 Completed cycle inspection June 13, 2011 Received application of appeal

During the cycle inspection it was noted that there was roof and soffits needed to be repaired or replaced. In addition the wall in the unoccupied apartment 1216 ½ is bowing inward, we have requested that the wall either be repaired or that documentation be provided from a structural engineer that the foundation is sound. The petitioner is requesting an additional 90 days to complete this work due to damage done by recent

storms to other properties that they own.

Staff recommendation:

Grant the extension of time.

Conditions:

All roof, soffit, guttering, painting and basement structural items must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline:

September 13, 2011

Attachments:

Application for appeal, Cycle Report



Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 Hand@bloomington.in.gox

Property Address: 1214 and 1216 i	North Grant Street		
Petitioner's Name: CS Property Ma	nagement		
Address: 225 North Washington Stre	eet		
City: Bloomington	State: Indiana	Zip Code: 47408	
Phone Number: (812) 330-1411	E-mail Address: jr	obinson@cspropertymanagement.com	
Owner's Name: Stephen and Conn	ie Ferguson		
Address: 225 North Washington Stre	et		
City: Bloomington	State: Indiana	Zip Code: 47408	
Phone Number: 812-330-1411	E-mail Address: jro	obinson@cspropertymanagement.com	
1214-Richard Shuya and Occupants: 1216-Timothy Bird	Nick Busche	,	23
 That the exception is consistent when the health, safety, and general welfar 	with the intent and pore.	in order for the Board to consider the urpose of the housing code and promote the the the housing code and promote the exception is to apply will not be	tes public
	1 00 00 000 TODA	rom the following drop down menu:	
Variance Type: An extension of tim	e to complete repairs. (I	Petition Type: TV)	

Reminder:

A \$20.00 filing fee must be submitted with the Appeal Application or the application will not be considered to be complete! A completed application has to be submitted prior to the meeting application deadline in order to be placed on that months agenda!

(Will be assigned by BHQA)

11-TV-93

Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - . 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

	The interior repairs requested will be completed within the 60 days allotted. However, we need additional time to complete the external repairs: repair or replace damaged roofing, repair or replace damaged soffit/fascia, secure guttering to the structure and scrape/paint exterior surfaces. In addition, HAND has required that we repair the basement wall or have an engineer certify that it is sound. Our properties suffered a lot from the recent storm damage and we have been set back. I ask that we are allowed an additional 90 days to complete the above-listed items. Thank you for your consideration.
	terns. Hank you for your consideration.
Ì	
١	

	* •	
Signature (Required)		

Name (Print): Jill Robinson for CS Property Management

Date:

6/7/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



City of Bloomington Housing and Neighborhood Development

Cycle Report

533

OWNERS

FERGUSON, STEPHEN L. 225 N. WASHINGTON ST. BLOOMINGTON, IN 47408 FERGUSON, CONNIE M. 225 N. WASHINGTON ST. BLOOMINGTON, IN 47408

AGENT

CS PROPERTY MANAGEMENT 225 N. WASHINGTON ST. **BLOOMINGTON IN 47408**

Prop. Location: 1214 & 1216 N GRANT ST

Date Inspected: 04/11/2011 Inspectors: Maria McCormick Primary Heat Source: Gas

Property Zoning: RH

Number of Stories: 1

Number of Units/Structures: 4 / 1 Number of Bedrooms: 1 & 2 Max # of Occupants: 2 & 4 Foundation Type: Basement

Attic Access: No

Accessory Structure: None

VARIANCE

12/03/1980 Granted a variance to the minimum light and ventilation requirements at 1214-1/2 N. Grant. Granted a variance to the minimum light and ventilation requirement in the bedroom and to the minimum light requirement in the living room at 1216-1/2 N. Grant.

INTERIOR:

1214 N. Grant -

401 N. Morton Street

Fax: (812) 349-3582

Bloomington, IN 47404

Living Room 11-2 x 15-2:

Repair the entry door to be weather tight. No gaps shall be visible around the edges, PM-

Repair the install a storm door to function as intended. PM-102.8 & PM-303.15

Repair or replace existing smoke detector in a manner so that it functions as intended. PM-704.1

60

City Hall

www.bloomington.in.gov

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421

Housing Division: (812) 349-3401

Kitchen 9-3 x 8-8:

Replace the missing protective cover for the exhaust fan above the stove so that it may function as intended. PM-403.3

South Bedroom 11-3 x 11-5:

Repair or replace existing smoke detector in a manner so that it functions as intended. PM-704.1

Existing Egress Window Measurements:

Height: 24 inches Width: 34 inches

Sill Height: 27 ½ inches Openable Area: 5.66 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Hallway:

Repair or replace existing smoke detector in a manner so that it functions as intended. PM-704.1

Mechanical Closet:

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

North Bedroom 8-11 x 11-4:

Repair or replace existing smoke detector in a manner so that it functions as intended. PM-704.1

Existing Egress Window Measurements:

Height: 24 inches Width: 34 inches

Sill Height: 27 ½ inches Openable Area: 5.66 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Bathroom:

No violation noted.

1216 N. Grant -

Living Room 11-2 x 15-2; Kitchen 9-3 x 8-8:

No violation noted.

North Bedroom 8-11 x 11-4:

Determine the source and eliminate the water leak on the northwest corner of the room. PM-504.1

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials. Properly repair the ceiling where there is damage from the ceiling. PM-304.3

Interior walls shall be free of holes, cracks, peeling paint and deteriorated drywall/plaster. Properly repair the walls where there is damage form the leak. PM-304.3

Existing Egress Window Measurements:

Height: 24 inches Width: 34 inches

Sill Height: 27 ½ inches Openable Area: 5.66 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Laundry Closet:

Replace the missing protective cover for the light fixture. PM-605.1

Bathroom:

No violation noted.

South Bedroom 11-3 x 11-5:

No violation noted.

Existing Egress Window Measurements:

Height: 24 inches Width: 34 inches

Sill Height: 27 ½ inches Openable Area: 5.66 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Furnace Room (Located in 1216 ½ N. Grant):

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

Temperature/pressure relief (TPR) valve discharge tubes:

- shall not be reduced in size from the valve outlet
- shall be rigid galvanized, rigid copper, or any CPVC pipe
- shall not have a threaded discharge end
- drain by gravity
- shall have a minimum 1" air gap where discharging into a sanitary drain, or an approved air break
- shall extend to within 6" of floor. PM-505.4

1216 1/2 N. Grant -

Properly repair the south basement wall in a manner that allows it to properly & safely support normally imposed loads. It is bowing inward. An alternative to repairing the wall is to provide signed and stamped documentation from a structural engineer that the basement walls are structurally sound and capable of supporting the upper level. PM-303.5, PM-304.2, 102.03

1214 1/2 N Grant --

This unit is vacant and was not inspected at the time of inspection. It must be inspected and brought into compliance prior to being rented.

EXTERIOR:

Repair or replace damaged or deteriorating roofing. This is to be done in a workmanlike manner and includes but is not limited to damaged or deteriorating roofing material, sheathing, and all structural members. PM-303.4 & PM-303.7

Properly repair or replace damaged/deteriorated soffit/fascia in a manner that seals all openings. PM-303.6 & PM-303.7

Secure guttering to the structure. PM-303.7

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (This item only has a compliance deadline of April 11, 2012.)

Replace the broken/missing outlet cover plate for the outlet adjacent to the entrance door of unit 1216. PM-605.1

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-94

Address:

512 W. Dixie St.

Petitioner:

Mary Morrisette, Trust Administrator, Old National-WMG

Inspector:

Norman Mosier

Staff Report:

February 25, 2011- Conducted Cycle Inspection June 6, 2011 Sent Remaining Violations Report

June 16, 2011 Attempted Cycle Inspection - Cancelled by Petitioner

Petitioner is requesting an extension of time to complete repairs. The structure incurred extensive storm damage to the exterior.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the


possibility of fines.

Compliance Deadline: August 15, 2011

Attachments: Cycle Report, Remaining Violations Report, Petitioner's Letter, Photos



Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420



Petitioner's Name: MARY MORRISETTE, TRUST F.	DOMINISTRATOR DLD NATIO	ON A L-WMG
	7175400	
Petitioner's Address & Phone Number: 2801Buick-CADIL	Rup RI	Talifornia
Petitioner's Address & Phone Number: & 101BUICK-LHOIL	LACILLO, DIOOMINGTOW,	LN 47701
Owner's Name: ELAINE PAPIE TRUST		
349-5981		
Owner's Address & Phone Number: 2801 Buck-CADIC	De Blun Bloom Muchally	FIL MANOL
Office S Address & I home Fidulibet. Dio 27 7 July 27 9707	21.0 22.0., 21.00 11.1041010,2	-10 -7-1 km
Address of Property: 512 W. DIXIE St. B	•	
Address of Froperty. 3/8 33 5/2/2 13		
Occupant(s) Name(s): 54wat BaggERLY		
The following conditions must be found in each case in order for the Bost. That the value of the area about the property to which the exception is to	and to consider the request:	
2. That the exception is consistent with the intent and purpose of the housing		
safety, and general welfare.	and odde and promotos public homas,	
Identify the variance type that you are requesting from the following list	t and attach the required information.	•
Y	, n	•
A. An extension of time to complete repairs. (Petition type: TV Specify the items that need the extension of time to co		
Explain why the extension is needed	mprote .	
Specify the time requested		
B. A modification or exception to the Housing Property Maint	tenance Code. (Petition type: V)	•
Specify the code reference number you are appealing		•
→ Detail why you are requesting the variance	•	
Specify the modifications and or alterations you are st		
C. Relief from an administration decision. (Petition type: AA)		
Specify the decision being appealed and the relief you	i are seeking	
D. Rescind a variance. (Petition type: RV)	* *	
Detail the existing variance ⇒ Specify the reason the variance is no longer needed		
Specify the reason the variance is no longer needed	·	
I certify that all information submitted with this request is correct and l	have enclosed the \$20.00 filing fee.	
Ola national Benk Tuster		
Signature: Bus Masa Mossas The	(Will be assigned by BHQA)	
Name (print): MARY MORRIS ette	11-71-94	
Name (print): MARY MORRISETTE	Petition Number:	



Application for Appeal
To The
Board of Housing Quality Appeals
P.O. Box 100
Bloomington, IN 47402
812-349-3420

(Please write a brief narrative in the space provided below. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting.)

We were Completing the repair in occardance with the March 4,2011 Pentil Permit Inform letter and Cycle Report, When the storms, Winds, torrade took out four true at this property. Iwo of the true were on the property and one hit the Corners of the last sew of the house and the Corner of the garage. We had the true removed and are Currently separing the house, koog, gutter and garage. The total domaged were Istimater in excess of 12,000. We would appreciate an extension of (2) mor as to complete le Notional - WMG, Truster Signature: By: Mary morresette Date: 6-13-11



City of Bloomington Housing and Neighborhood Development

Cycle Report

1313

OWNERS

APPLE, ELAINE EST C/O MO. BANK/ MARY MORRISETTE P.O. BOX 2329 BLOOMINGTON, IN 47402

Prop. Location: 512 W DIXIE ST

Date Inspected: 02/25/2011 Inspectors: Norman Mosier Primary Heat Source: Gas

Property Zoning: RC

Number of Stories: 1

Number of Units/Structures: 1/1

Number of Bedrooms: 2 Max # of Occupants: 3 Foundation Type: Basement

Attic Access: Yes

Accessory Structure: Garage

INTERIOR:

Enclosed Front Porch:

No violations noted.

Living Room 11 x 9:

Repair/replace the cracked front door, and repair the door to latch properly. PM-303.15

Properly install a weather strip on the entrance door to exclude air infiltration as completely as possible, and to substantially exclude rain. PM-303.13

Kitchen:

Replace the loud garbage disposal. PM-504.1

Hallway:

No violations noted.

Attic:

No violations noted.

68

401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582

City Hall

Rental Inspections: (812) 349-3420

www.bloomington.in.gov

Neighborhood Division: (812) 349-3421 Housing Division: (812) 349-3401

Bathroom:

Repair the doorknob to function as intended, knob falls off. PM-304.6

Interior walls shall be free of holes, cracks, peeling paint and deteriorated drywall/plaster, left end of tub/shower. PM-304.3

S Bedroom 9 x 9:

No violations noted.

Existing Egress Window Measurements: Dbl Hung: Const. Yr. - 1925

Height: 22 inches Width: 29 inches

Sill Height: 25.5 inches Openable Area: 4.43 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

N Bedroom 11 x 9:

No violations noted.

Existing Egress Window Measurements: Dbl Hung: Const. Yr. - 1925

Height: 23.5 inches Width: 27.25 inches Sill Height: 25 inches

Openable Area: 4.45 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Closet:

No violations noted.

BASEMENT

Stairway:

No violations noted.

Main Room:

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level: 0 parts per million (ppm)

Acceptable level in a living space: 9 ppm

Maximum concentration for flue products: 50 ppm PM-603.1

GARAGE:

Repair the door to fit the door jamb, and repair the door to latch properly. PM-303.15

Scrape and paint the entry door, paint deteriorated, wood exposed. PM-304.3

Clean debris from the roof, gutters and downspouts. PM-303.7

Remove the vines that are growing on the structure. PM-102.8, PM-302.4, & PM-303.1

EXTERIOR:

Clean debris from the roof, gutters and downspouts. PM-303.7

Remove the vines that are growing on the structure. PM-102.8, PM-302.4, & PM-303.1

Remove and properly dispose of yard waste/brush piles/dead limbs. PM-102.3 & PM-302.1

Trim all tree branches away from the siding and roofline to maintain a 3' clearance: PM-302.4.1

Secure guttering to the structure on the west side of structure. PM-303.7

Repair the NW gate on the fence to latch properly. PM-302.7.1

Replace the missing gutter on the east side of structure. PM-303.7

Repair the damaged basement window well frame and window cover. PM-303.13

Trim the dead limbs from the trees in the front yard. PM-302.4.1

Clear the overgrowth from the front (south) gate entrance to property. PM-301.2

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



City of Bloomington Housing and Neighborhood Development

REMAINING VIOLATIONS REPORT

JUN 0 6 2011

1313

OWNERS

APPLE, ELAINE EST C/O MO. BANK/ MARY MORRISETTE P.O. BOX 2329 BLOOMINGTON, IN 47402

Prop. Location: 512 W DIXIE ST

Date Inspected: 02/25/2011 Inspectors: Norman Mosier Primary Heat Source: Gas

Property Zoning: RC

Number of Stories: 1

Number of Units/Structures: 1 / 1

Number of Bedrooms: 2 Max # of Occupants: 3

Foundation Type: Basement

Attic Access: Yes

Accessory Structure: Garage

REINSPECTION REQUIRED

This report is your final notice from the Housing and Neighborhood Development Office that this rental property continues to be in violation of the Housing-Property Maintenance Code of Bloomington.

If you have made all of the repairs on this report, contact our office immediately to schedule the required re-inspection.

Failure to make repairs or to schedule the required re-inspection will result in this matter being referred to the City Legal Department. Legal action may be initiated against you under Section 16.12.100 of the Bloomington Municipal Code.

It is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection. Our mailing address and telephone number are listed below.

INTERIOR:

Enclosed Front Porch:

No violations noted.

City Hall

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421

Housing Division: (812) 349-3401

401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582

Living Room 11 x 9:

Repair/replace the cracked front door, and repair the door to latch properly. PM-303.15

Properly install a weather strip on the entrance door to exclude air infiltration as completely as possible, and to substantially exclude rain. PM-303.13

Kitchen:

Replace the loud garbage disposal. PM-504.1

Hallway:

No violations noted.

Attic:

No violations noted.

Bathroom:

Repair the doorknob to function as intended, knob falls off. PM-304.6

Interior walls shall be free of holes, cracks, peeling paint and deteriorated drywall/plaster, left end of tub/shower. PM-304.3

S Bedroom 9 x 9:

No violations noted.

Existing Egress Window Measurements: Dbl Hung: Const. Yr. - 1925

Height: 22 inches Width: 29 inches

Sill Height: 25.5 inches Openable Area: 4.43 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

N Bedroom 11 x 9:

No violations noted.

Existing Egress Window Measurements: Dbl Hung: Const. Yr. - 1925

Height: 23.5 inches Width: 27.25 inches Sill Height: 25 inches

Openable Area: 4.45 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Closet:

No violations noted.

BASEMENT

Stairway:

No violations noted.

Main Room:

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

GARAGE:

Repair the door to fit the door jamb, and repair the door to latch properly. PM-303.15

Scrape and paint the entry door, paint deteriorated, wood exposed. PM-304.3

Clean debris from the roof, gutters and downspouts. PM-303.7

Remove the vines that are growing on the structure. PM-102.8, PM-302.4, & PM-303.1

EXTERIOR:

Clean debris from the roof, gutters and downspouts. PM-303.7

Remove the vines that are growing on the structure. PM-102.8, PM-302.4, & PM-303.1

Remove and properly dispose of yard waste/brush piles/dead limbs. PM-102.3 & PM-302.1

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. PM-302.4.1

Secure guttering to the structure on the west side of structure. PM-303.7

Repair the NW gate on the fence to latch properly. PM-302.7.1


Replace the missing gutter on the east side of structure. PM-303.7

Repair the damaged basement window well frame and window cover. PM-303.13

Trim the dead limbs from the trees in the front yard. PM-302.4.1


Clear the overgrowth from the front (south) gate entrance to property. PM-301.2


When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)

















Elaine D. Apple Irrevocable Trust Property: 512 W. Dixie Old National Wealth Management Trustee









Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-95

Address:

516 S. Jordan Ave.

Petitioner:

Laurence Ayres

Inspector:

John Hewett

Staff Report: May 5, 2011

Conducted Cycle Inspection

May 19, 2011

Report sent

June 6, 2011

Received Appeal

June 13, 2011

Received Fee

During the cycle inspection a number of items were cited including the glazing compound on the windows and deterioration of the concrete of the front stoop. The owner is asking for additional time to attend to these items.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.


Compliance Deadline:

October 19, 2011

Attachments:

Cycle Inspection Report, Petitioner's letter





Application For Appeal To The Wo CW Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402

3944

812-349-3420 hand@bloomington.in.gov

Property Address: 5	16 South Jorda	n Avenue	Bloomington, Ind	iana 47401	
Petitioner's Name:	_aurence V. Ayr	es			
Address: 1605 Snowb	owl Road				
City: Missoula		State:	Montana		Zip Code: 59808
Phone Number: (40	06) 360-8757	E-mail	Address: Ivayre	s@msn.con	n .
Owner's Name: Lau	rence V. Ayres			,	
Address: 1605 Snowb	owl Road				
City: Missoula	reconstruction of the second o	State:	Montana	· ************************************	Zip Code: 59808
Phone Number: 40	06-360-8757	E-mail	Address: Ivayre	s@msn.com	1
Occupants: Lauren Ay	/res; Jenn Hugh	es			
 That the exception health, safety, and g 	is consistent v general welfar	vith the e.	intent and purpo	se of the I	he Board to consider the request: housing code and promotes public on is to apply will not be adversely
ldentify the varianc	e type that y	ou are r	equesting from	the follo	wing drop down menu:
Variance Type: An e	xtension of time	e to comp	olete repairs. (Petit	ion Type: T	v)
Reminder: A \$20.00 filing fee mu Application or the ap complete! A complete prior to the meeting a	plication will r ed application application de	not be co	onsidered to be be submitted	/	(Will be assigned by BHQA) 11 - TV - 95 n Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

,											
A.		An	extension		of	time	to		complete	e	repairs.
1.	Front	porch		spalling		north		and		pane	glazing:
							but have				
Loca	l contra	ctors are a	lso delayed	such tha	t a July i	19, 2011	completion	date u	using their s	ervices is	unlikely.
Also,	, a	prop	er rep	air v	without	lawr	ı dama	ige -	or v	vork	vehicles
park	ed			on			Jordan	1			Avenue
requ			_	n this		•		•	ny perso		tendance.
							st, 2011, and				
is ı	not in	the wal	king path	way to	the en	try of	the house	, it	is not a	safety	problem,
but			one	•		her		of			esthetics.
Like	wise, the	e window g			nsuming.	All wind	ows are enc	losed b	ehind storm	window	s and the
hom	e	is	e	fficiently		air-coi	nditioned,		and		therefore
this		proble	m	is	í	also	one		of		esthetics.
The		rem	aining		items		on		Mr.		Hewetts'
list	are	more	easily		nplished			be	attended	d to	first.
3. I	reques	t and exte	ension of	3 months	, to Oc	tober 19	, 2011 to	prop	erly comple	ete these	e repairs.

Signature (Required):	Myus		
Name (Print): Laurence V. Ayres		Date:	6/1/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



City of Bloomington Housing and Neighborhood Development

Cycle Report

3944

OWNERS

AYRES, LAURENCE V. 1605 SNOWBOWL ROAD MISSOULA, MI 59808

AGENT

AYRES, LAUREN C. 516 S. JORDAN AVE **BLOOMINGTON IN 47401**

Prop. Location: 516 S JORDAN AVE

Date Inspected: 05/05/2011 Inspectors: John Hewett Primary Heat Source: Gas

Property Zoning: RC Number of Stories: 2

Number of Units/Structures: 1 / 1

Number of Bedrooms: 4 Max # of Occupants: 3 Foundation Type: Basement

Attic Access: N/A Accessory Structure:

VARIANCE

07/23/2004 The Northeast room of the basement shall not be used for sleeping purposes.

Monroe County Assessor's records indicate this structure was built in 1942. There were no minimum emergency egress requirements at the time of construction.

Interior

Kitchen

12-10 x 8-5

Replace the empty fire extinguisher. A minimum 1A 10BC classification fire extinguisher shall be mounted in a visible, accessible location, in or adjacent to the kitchen, away from the range, and in the path of egress. The securing mechanism must be no more than 5 feet above the floor. PM-704.3.

Living room

11-8 x 20-3

Install a cover plate on the 220 volt outlet on the north wall. PM-605.1

89

Fax: (812) 349-3582

Housing Division: (812) 349-3401

Properly ground the electrical receptacle on the west wall. If the receptacle is on an ungrounded system, it is acceptable to install a 2-pole, ungrounded receptacle, or a GFCI receptacle. PM-605.1

SE bedroom

10-11 x 12-9

Properly ground the electrical receptacles. If the receptacles are on an ungrounded system, it is acceptable to install 2-pole, ungrounded receptacles, or a GFCI receptacles. PM-605.1

Existing Egress Window Measurements:

Height: 24.5 inches Width: 34.75 inches Sill Height: 27 inches Openable Area: 5.9 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

SW bedroom

10-0 x 10-8

Properly ground the electrical receptacles. If the receptacles are on an ungrounded system, it is acceptable to install 2-pole, ungrounded receptacles, or a GFCI receptacles. PM-605.1

Existing Egress Window Measurements:

Height: 24.5 inches Width: 26.75 inches Sill Height: 27 inches Openable Area: 4.55 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Bathroom

No violations noted.

Dining room

9-0 x 9-6

No violations noted.

2nd Floor

Bedroom 12-3 x 36-5

Existing Egress Window Measurements: casement

Height: 48 inches Width: 24 inches Sill Height: 24 inches Openable Area: 8 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Basement

Bathroom

No violations noted.

Storage room11-0 x 11-10

No violations noted.

S bedroom

10-7 x 11-1

Existing Egress Window Measurements:

Height: 33 inches Width: 23 inches Sill Height: 44 inches Openable Area: 5.27 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Main room

No violations noted.

Laundry room

Eliminate all unused openings in service panel/junction box, by installing approved rigid knockout blanks. PM-604.3

Exterior

Replace all missing and cracked glaziers compound on the windows. PM-303.13.1

Repair the loose siding on the west wall. PM-303.6

Properly repair the front concrete porch floor to be in good repair. The surface of the slab shall be smooth and free of spalling and cracking. PM-303.10

Other requirements

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

13 July 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-096

Address:

500 E. Graham Pl.

Petitioner:

Candi Mullis

Inspector:

Michael Arnold

Staff Report:

13 May 2011

Cycle Inspection

23 May 2011

Sent Report

14 June 2011

Received Appeal

During the cycle inspection it was noted that the egress windows do not meet the minimum requirements for emergency egress for structures built in 1983. The petitioner is requesting additional time to request a variance from the Indiana Department of Homeland Security.

Staff recommendation: Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadlines stated below, or this case will be turned over to the City of Bloomington

Legal Department for further action including the possibility of fines.

Compliance Deadline: 27 July 2011

Hallway Smoke Detector

13 September 2011


All other violations

Attachments: Inspection Report, Application



Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100

Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov



BY:____ Property Address: 500 E Graham Place Petitioner's Name: Candi Mullis Address: 621 N Walnut St/PO Box 1112 City: Bloomington State: Indiana **Zip Code:** 47402 E-mail Address: cmullis@parkermgt.com Phone Number: (812) 339-2115 Owner's Name: Norman Grandos Address: 5605 Autumn Woods Trail City: Fort Wayne State: Indiana **Zip Code:** 46835 Phone Number: 260-486-5152 E-mail Address: Occupants: Stacey Foley

The following conditions must be found in each case in order for the Board to consider the request:

- 1. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety, and general welfare.
- 2. That the value of the area about the property to which the exception is to apply will not be adversely affected.

Identify the variance type that you are requesting from the following drop down menu:

Variance Type: An extension of time to complete repairs. (Petition Type: TV)

Reminder:

A \$20.00 filing fee must be submitted with the Appeal Application or the application will not be considered to be complete! A completed application has to be submitted prior to the meeting application deadline in order to be placed on that months agenda!

(Will be assigned by BHQA)

11-TV-96

Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

I am requesting an extension of time to complete repairs to allow to complete the window egress variance requested. The next boa am requesting an extension of time till August 15, 2011.	w the State of Indiana Dept. of Homeland Security ard meeting for a variance will be August 2, 2011. I
Signature (Required): Mame (Print): Candi Mullis	Date: 6/2/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form

417

OWNERS

=====

GRANDOS, NORMAN 5605 AUTUMN WOODS TRAIL FORT WAYNE, IN 46835

AGENT

=====

PARKER REAL ESTATE MANAGEMENT PO BOX 1112 BLOOMINGTON IN 47402

Prop. Location: 500 E GRAHAM PL

Date Inspected: 05/13/2011 Inspectors: Mike Arnold Primary Heat Source: Electric

Property Zoning: RM Number of Stories: 2 Number of Units/Structures: 1 / 1

Number of Bedrooms: 4 Max # of Occupants: 5 Foundation Type: Basement

Attic Access: Yes

Accessory Structure: none

Notes:

According to Monroe County records, this structure was built in 1983. The minimum requirements for emergency egress at that time were:

Height:

24 inches

Width:

18 inches

Sill Height: 48 inches

Openable Area: 4.75sq. ft.

Interior:

Lower Level:

Main Room:

This room is not approved for sleeping purposes. A tenant violation has been issued.

Repair the hole in the paneling adjacent to the door to the rear room. PM-304.3

West Room (12-0 x 10-0):

The emergency egress window does not meet the minimum requirements for a one and two family dwelling/multi-unit structure built in 1983:

Openable area required:

4.75sq. ft.

Existing area:

4.67sq. ft.

Clear width required:

18"

Existing width: 34.5"

Clear height required:

24"

Existing height:

19.5"

Maximum sill height:

48" above finished floor Existing sill:

38"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

Utility/Bathroom:

No violations noted

Main Level:

Entryway:

Seal the flooring at the entry door. PM-304.3

Living Room (15-6 \times 13-7):

Provide operating power to smoke detector. PM-704.1

Replace the missing handle on the sliding door. PM-303.15

Kitchen (10-5 x 7-1), ½ Bathroom:

No violations noted.

Upper Level:

Front Bedroom (13-9 x 9-8), Middle Bedroom (9-7 x 8-2):

The emergency egress window does not meet the minimum requirements for a multi-unit structure built in 1983.

Openable area required: 4.75sq. ft. Existing area: 5.1 sq. ft. Clear width required: 18" Existing width: 31.25"

Clear height required: 24" Existing height: 23.5"

Maximum sill height: 48" above finished floor Existing sill: 32"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

Rear Bedroom (11-6 \times 8-5):

This egress window is blocked by the placement of furniture. A tenant violation has been sent.

Measure this window at reinspection.

No violations noted

Bathroom:

Scrape and paint interior surfaces where paint is peeling or wood is exposed. PM-304.3

Repair the water damage at the wall on both ends of the front of the tub. PM-304.3

Hallway:

Secure the smoke detector to the wall. PM-704.1

Attic:

Not accessible

Exterior:

Label the main electrical shutoff to the unit. PM- 605.1

Required Documentation:

Complete the enclosed registration form. A street address is required for both owner and agent. This form must be signed by the owner. BMC16.12.060

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

13 July 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-097

Address:

507 E. Graham Pl.

Petitioner:

Candi Mullis

Inspector:

Michael Arnold

Staff Report:

13 May 2011

Cycle Inspection

23 May 2011

Sent Report

14 June 2011

Received Appeal

During the cycle inspection it was noted that the egress windows do not meet the minimum requirements for emergency egress for structures built in 1983. The petitioner is requesting additional time to request a variance from the Indiana Department of Homeland Security.

Staff recommendation: Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington

Legal Department for further action including the possibility of fines.

Compliance Deadline: 13 September 2011

Attachments: Inspection Report, Application



Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 JUN 1 3 2011

hand@bloomington.in.gey

Property Addres	s: 507 E Graham P	lace	
Petitioner's Nam	e: Candi Mullis		
Address: 621 N W	/alnut St/ PO Box 1	. 112	
City: Bloomington	1	State: Indiana	Zip Code: 47402
Phone Number:	(812) 339-2115	E-mail Address: cmullis@	parkermgt.com
Owner's Name:	Richard Lin		
Address: 959 Clin	ton Rd		
City: Los Altos		State: California	Zip Code: 94024
Phone Number:	760-735-5847	E-mail Address:	
Occupants: Drew	simmonds, Steve	n Sullivan	
1. That the except health, safety, a	ion is consistent nd general welfa	with the intent and purposere.	ler for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely
ldentify the vari	ance type that y	ou are requesting from t	he following drop down menu:
Variance Type:	An extension of tin	ne to complete repairs. (Petitio	n Type: TV)
Application or the complete! A com	e application will pleted applicatio ing application d	ted with the Appeal not be considered to be in has to be submitted leadline in order to be	(Will be assigned by BHQA) $//-7V-97$ Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

am requesting an extension of time to co o complete the window egress variance re m requesting an extension of time till Aug	equested. The next board	meeting for a variance will I	oe August 2, 2011.
ignature (Required):	- Mallo	-	
Name (Print): Candi Mullis		Date:	6/2/11

1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).

2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form

423

OWNERS

======

LIN, RICHARD 959 CLINTON ROAD LOS ALTOS, CA 94024

AGENT

PARKER REAL ESTATE MANAGEMENT

PO BOX 1112

BLOOMINGTON IN 47402

Prop. Location: 507 E GRAHAM PL

Date Inspected: 05/13/2011 Inspectors: Mike Arnold

Primary Heat Source: Electric

Property Zoning: RM Number of Stories: 2 Number of Units/Structures: 1 / 1

Number of Bedrooms: 4 Max # of Occupants: 5 Foundation Type: Basement

Attic Access: Yes

Accessory Structure: none

Notes:

According to Monroe County records, this structure was built in 1983. The minimum requirements for emergency egress at that time were:

Height:

24 inches

Width:

18 inches

Sill Height: 48 inches

Openable Area: 4.75sq. ft.

Interior:

Lower Level:

Main Room:

The emergency egress window does not meet the minimum requirements for a one and two family dwelling/multi-unit structure built in 1983:

Openable area required:

4.75sq. ft.

Existing area:

4.67sq. ft.

Clear width required:

18"

Existing width: 34.5"

Clear height required:

24"

Existing height:

19.5"

Maximum sill height:

48" above finished floor Existing sill:

38"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the Department of Homeland Security on the Fire Prevention and Building Safety Commission's web site at www.in.gov/dhs/2375.htm.

Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

Utility/Bathroom:

Seal the floor along the wall adjacent to the stool. PM-304.4

Main Level:

Living Room (15-6 x 13-7), ½ Bathroom:

No violations noted.

Kitchen (10-5 x 7-1):

Every window shall be capable of being easily opened and held in position by its own hardware. PM-303.13.2

Upper Level:

Front Bedroom (13-9 x 9-8), Middle Bedroom (9-7 x 8-2), Rear Bedroom (11-6 x 8-5):

The emergency egress window does not meet the minimum requirements for a multi-unit structure built in 1983.

Openable area required:	4.75sq. ft.	Existing area:	5.1 sq. ft.
Clear width required:	18"	Existing width: 31.25"	•
Clear height required:	24"	Existing height:	23.5"
Maximum sill height:	48" above fini	shed floor Existing sill:	32"

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.02.040 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

Bathroom:

No violations noted

Attic:

Not accessible

Exterior:

Label the main electrical shutoff to the unit. PM-605.1

Required Documentation:

Complete the enclosed registration form. A street address is required for both owner and agent. This form must be signed by the owner. BMC16.12.060

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs and to secure a state egress

variance from the Fire Prevention and Building Safety Commission,

Department of Homeland Security.

Petition Number:

11-TV-98

Address:

1736 N. Lincoln St.

Petitioner:

Candi Mullis/Parker Real Estate Mgmt.

Inspector:

Norman Mosier

Staff Report:

May 9, 2011 – Conducted Cycle Inspection

June 14, 2011 – Received BHQA Appeal

Petitioner is requesting an extension of time to complete repairs and to apply to the State of Indiana for and egress window variance from the Fire Prevention and Building Safety Commission, Department of Homeland Security.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline: August 15, 2011 For all Violations

September 13, 2011 For the State Egress Variance

Attachments: Cycle Report, BHQA Application, Petitioner's Letter




prior to the meeting application deadline in order to be

placed on that months agenda!

Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

Petition Number:



Property Address	s: 1736 N Lincoln S	5t	BY:
Petitioner's Nam			11.,
Address: 621 N W		112	
City: Bloomingtor		State: Indiana	Zip Code: 47402
Phone Number:	(812) 339-2115	E-mail Address: cmullis@	parkermgt.com
Owner's Name:	Chesters Rentals, L	LC	
Address: 1924 S. [Dan Jones Rd		
City: Avon		State: Indiana	Zip Code: 46123
Phone Number:	317-563-2845	E-mail Address:	
Occupants: Mitch	nell Morris, Jared H	arnish	
1. That the except health, safety, a	ion is consistent nd general welfa	with the intent and purpose re.	ler for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely
Identify the vari	ance type that y	you are requesting from t	he following drop down menu:
Variance Type:	An extension of tin	ne to complete repairs. (Petitio	n Type: TV)
Application or the	e application will	tted with the Appeal not be considered to be on has to be submitted	(Will be assigned by BHQA) $11 - 7V - 98$

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

•		

2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



City of Bloomington Housing and Neighborhood Development

Cycle Report

3521

OWNERS

CHESTERS RENTALS, LLC 1924 S. DAN JONES ROAD AVON, IN 46123

AGENT

PARKER REAL ESTATE MGMT. P.O. Box 1112

Bloomington, In. 47402

Prop. Location: 1736 N LINCOLN ST

Date Inspected: 05/09/2011 Inspectors: Norman Mosier

Primary Heat Source: Electric Property Zoning: RH

Number of Stories: 2

Number of Units/Structures: 1 / 1

Number of Bedrooms: 2 Max # of Occupants: 4

Foundation Type: Crawl Space

Attic Access: Yes

Accessory Structure: None

Egress multi-family 89 – 91

The Monroe County Assessor's records indicate that this structure was built in 1990. Minimum egress requirements for a multi-family structure built or altered between 1989

and 1991 are: Openable area: 5.7 Sq. Ft.

Clear width: 20 inches Clear height: 24 inches Sill height: 44 inches

INTERIOR:

Living Room 17 x 12:

No violations noted.

Kitchen:

Repair the GFCI to the left of sink to have correct polarity, hot/neutral reverse. PM-605.1

Bath/Laundry room:

Secure toilet to its mountings. PM-504.1

107

Housing Division: (812) 349-3401

City Hall

Hall Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421

401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582

UPSTAIRS

Stairway/Hallway:

No violations noted.

W Bedroom13 x 10-6, E Bedroom 13 x 11:

Existing Egress Window Measurements: Dbl Hung pop out: Const. Yr. - 1990

Height: 20 inches Width: 35 inches Sill Height: 36 inches Openable Area: 4.86 sq. ft.

The emergency egress window does not meet the minimum requirements for a multi-unit structure built in 1990:

Openable area required: 5.7 sq. ft. Existing area: 4.86sq. ft.

Clear width required: 20 inches

Clear height required: 24 inches

Existing width: 35 inches

Existing height: 20 inches

Maximum sill height: 44" above finished floor Existing sill: 36 " above finished floor

The emergency egress window does not meet the minimum code requirements for the time the structure was built. For that reason, the City will not issue a rental permit until either the window is altered or replaced to meet the code requirement at the time of construction, or you apply for an egress variance with the Indiana Fire and Building Safety Commission. BMC-16.04.020 (b).

The State variance application forms are available at the *Department of Homeland Security* on the *Fire Prevention and Building Safety Commission*'s web site at www.in.gov/dhs/2375.htm. Scroll down to *Downloadable Forms and Documents* and click on *Variance Application and Instructions*. If you need any further clarification, the Commission can be reached at 317.233.5341.

W Bath/Shower Room:

No violations noted.

Toilet Room:

No violations noted.

E Bath/Shower Room:

No violations noted.

Attic:

No violations noted.

Crawlspace:

No violations noted.

EXTERIOR:

Properly label electrical service/meter disconnects with corresponding unit numbers. PM-701.2

Required Documentation:

Complete the enclosed registration form. A street address is required for both owner and agent. This form must be signed by the owner. BMC16.12.060

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-99

Address:

511 N. Fess Ave.

Petitioner:

Dennis Long

Inspector:

Norman Mosier

Staff Report:

March 17, 2011 - Conducted Cycle Inspection

June 6, 2011 Conducted Re-inspection

Petitioner is requesting an extension of time to completely renovate unit # 8. This renovation was in progress and noted in the Cycle Inspection Report. Petitioner is requesting until July 20, 2011 to have the renovation completed.

Staff recommendation:

Grant the extension of time.


Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline: August 20, 2011

Attachments: Cycle Report, Remaining Violations Report, Petitioner's Letter.



Property Address: 511 N. Fess				
Petitioner's Name: Dennis Long				
Address: 4409 Scenic Drive				
City: Bloomington	State: Indiana	Zip Code: 47408		
Phone Number: (812) 322-4058 E-mail Address: longrealestate@comcast.net				
Owner's Name: Long Real Estate I	nvestments L.P.			
Address: same				
City:	State:	Zip Code:		
Phone Number:	E-mail Address:	14		
Occupants:				
 That the exception is consistent health, safety, and general welfa 	with the intent and purpos are.	der for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely		
Identify the variance type that	you are requesting from t	he following drop down menu:		
Variance Type: An extension of tir	ne to complete repairs. (Petitic	on Type: TV)		
Reminder: A \$20.00 filing fee must be submi Application or the application wil complete! A completed application prior to the meeting application of placed on that months agenda!	I not be considered to be on has to be submitted	(Will be assigned by BHQA) $11 - 7V - 99$ Petition Number:		

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code, (Petition type; V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

A: an extension of time to co completely redecorated. The U	mplete repairs is requested for nit is not currently occupied. The	or Unit #8 until July 20th 2011. ne unit will not be occupied until a	This unit is being Aug. 15 2011.
,			
		·	

Signature (Required):

Name (Print): Dennis Long General Partner

Date:

6/9/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.





City of Bloomington Housing and Neighborhood Development

前 0 1 2011

Remaining Violations Report

387

OWNERS

LONG REAL ESTATE LLP 4409 SCENIC DRIVE BLOOMINGTON, IN 47408

Prop. Location: 511 N FESS AVE

Date Inspected: 03/17/2011

Inspectors: Norman Mosier

Primary Heat Source: Other

Property Zoning: RM

Number of Stories: 2

Number of Units/Structures: 8 / 1

Number of Bedrooms: 5-1br; 2 eff.; 1-2br.

Max # of Occupants: 2 per 1br.;2 per eff.; 4 per 2br.

Foundation Type: Basement

Attic Access: No

Accessory Structure: None

VARIANCE

04/14/2004 Special exception to the minimum light and ventilation requirements in the bathrooms of units #5 and #6.

REINSPECTION REQUIRED

This report is your final notice from the Housing and Neighborhood Development Office that this rental property continues to be in violation of the Housing-Property Maintenance Code of Bloomington.

If you have made all of the repairs on this report, contact our office immediately to schedule the required re-inspection.

Failure to make repairs or to schedule the required re-inspection will result in this matter being referred to the City Legal Department. Legal action may be initiated against you under Section 16.12.100 of the Bloomington Municipal Code.

It is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection. Our mailing address and telephone number are listed below.

113

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421 Housing Division: (812) 349-3401

NOTE:

- All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. PM-704.3
- This report has a sixty (60) day compliance deadline from the date the report is mailed from the Housing and Neighborhood Development Department (HAND) office unless otherwise stated following the individual listing of the violation(s). Failure to meet the deadline may result in the matter being turned over to the City of Bloomington Legal Department for the levying of fines and possible litigation.
- Only Units/Rooms with violations shall be listed on this report.

EGRESS WINDOW MEASUREMENTS ARE AS FOLLOWS FOR UNITS 1 THROUGH 5

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 49 inches Width: 17 inches Sill Height: 23 inches

Openable Area: 5.78 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

INTERIOR:

South Entry Hallway:

Repair the entry door to latch properly. PM-303.15

Unit 1 (1 Bedroom)

Living Room 20 x 13, + 11 x 8-6:

Repair the entry door to latch properly. PM-303.15

Kitchen 12 x 7:

Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1

Replace the broken smoke detector. PM-704.1

Re-locate the smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

C	Bathro	om: Repair the door to latch properly. PM-304.6
\subset		Repair the broken cold water faucet to function as intended. PM-504.1
C	Bedroo	om 13-6 x 11: Replace the old smoke detector. PM-704.1
	,	Re-locate the smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1
\subset		2 (EFF.) Room 23 x 13-6: Repair or replace existing smoke detector in a manner so that it functions as intended. PM-704.1
C	Kitche	n: Repair the faucet to eliminate the constant dripping. PM-504.1
C	/	Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1
C	Bathro	om: Repair the door to latch properly. PM-304.6
C		Repair the leaking hot water faucet handle on the sink to function as intended. PM-504.1
		Repair the exhaust fan to function as intended, clanking fan. PM-603.1
C		Interior walls shall be free of holes, cracks, peeling paint and deteriorated drywall/plaster. PM-304.3
C		Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials. PM-304.3
		3 (1 Bedroom)
	Kitche	Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1
(Repair the leaking sink faucet neck. PM-504.1

C	Bathroom: Repair the door to fit the door jamb and to latch properly. PM-304.6
C	The water supply system shall be installed and maintained to provide a supply of water to plumbing fixtures, devices and appurtenances in sufficient volume and at pressures adequate to enable the fixtures to function properly, safely, and free from defects and leaks (repair faucet in a manner so that there is adequate water pressure and volume to the sink). PM-505.3
	Bedroom 13-6 x 11: Repair the door to fit the door jamb and to latch properly. PM-304.6
\bigcirc	UNIT 4 (EFF.) Living Room 23 x 13-6: Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials. PM-304.3
C	<u>Kitchen:</u> Repair the stove burners to light as intended. PM-603.1
	Bathroom: Repair/replace the loud exhaust fan. PM-603.1
\subset	NORTH ENTRANCE Entryway: Repair the door to latch properly. PM-303.15
<u></u>	Lower Landing: Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials, @ south end of hallway. PM-304.3
	Stairway: Secure the handrail so it is capable of withstanding normally imposed loads. PM-304.5 (interior)
\bigcirc	<u>UNIT 5</u> (1 Bedroom) <u>Living Room 20 x 13 + 11 x 8-6:</u> Repair the entry door to latch properly. PM-303.15
C	Bathroom: Repair the door to latch properly. PM-303.15
C	Seal edge of floor covering adjacent to bathtub. PM-304.1
<u> </u>	Repair the cold water faucet on the sink, eliminate the constant dripping. PM-504.1

Bathroom: (continued)

Replace the broken cold water faucet handle. PM-504.1

Bedroom 13-6 x 11:

Tighten the loose receptacle on the north wall and replace the missing cover plate. PM-605.1

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 37 inches
Width: 16 inches
Sill Height: 33 inches
Openable Area: 4.11 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

UNIT 6 (EFF.)

Entry Hallway;

Repair the door to latch properly. PM-303.15

Bathroom:

Seal edge of floor covering adjacent to bathtub. PM-304.1

Secure the loose GFCI receptacle adjacent to the mirror. PM-605.1

Kitchen:

Properly ground the electrical receptacle @ sink. If the receptacle is on an ungrounded system, it is acceptable to install a 2-pole, ungrounded receptacle, or a GFCI receptacle. PM-605.1

Bedroom14 x 10:

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 37 inches Width: 16 inches Sill Height: 33 inches

Openable Area: 4.11 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

UNIT 7

Bedroom 11 x 10-10:

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 37 inches Width: 20.5 inches Sill Height: 33 inches Openable Area: 5.26 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Kitchen:

Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1

Repair the faucet sprayer on the sink to function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. PM-504.1

UNIT 8, NOTE: Finish turnover of unit, will check @ re-inspection.

Bedrooms:

Existing Egress Window Measurements: Slider: Const. Yr. - 1925

Height: 34.5 inches
Width: 16 inches
Sill Height: 43 inches
Openable Area: 3.83 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Lower Level Hallway:

Water Heater Closet:

Re-attach the bi-fold doors to stay in the track, function as intended. PM-304.6

EXTERIOR:

Clean debris from the roof, gutters and downspouts. PM-303.7

Replace the missing and deteriorated (cracked and peeling) glazing compound on the windows. PM-303.13

Secure the loose conduit on the north side of structure. PM-605.1

Repair the deteriorated front porch steps. PM-302.3

OTHER REQUIREMENTS:

Required documentation:

MG

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Boiler Room:



Boiler(s) are to be inspected every twelve months as per Indiana Code. A completed copy of the State of Indiana final Boiler Inspection report stating that the system is functioning as intended must be reviewed by this office before a Rental Occupancy Permit will be issued. PM-102.3, PM-504.1, & PM-603.1

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



City of Bloomington Housing and Neighborhood Development

Cycle Report

387

OWNERS

LONG REAL ESTATE LLP 4409 SCENIC DRIVE **BLOOMINGTON, IN 47408**

Prop. Location: 511 N FESS AVE

Date Inspected: 03/17/2011

Inspectors: Norman Mosier

Primary Heat Source: Other

Property Zoning: RM

Number of Stories: 2

Number of Units/Structures: 8 / 1

Number of Bedrooms: 5-1br; 2-Eff., 1-2br.

Max # of Occupants: 1 bd-2 ea., Eff.-2ea., 2 bd-2ea.

Foundation Type: Basement

Attic Access: No

Accessory Structure: None

VARIANCE

04/14/2004 Special exception to the minimum light and ventilation requirements in the bathrooms of units #5 and #6.

NOTE:

- All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. PM-704.3
- This report has a sixty (60) day compliance deadline from the date the report is mailed from the Housing and Neighborhood Development Department (HAND) office unless otherwise stated following the individual listing of the violation(s). Failure to meet the deadline may result in the matter being turned over to the City of Bloomington Legal Department for the levying of fines and possible litigation.
- Only Units/Rooms with violations shall be listed on this report.

Housing Division: (812) 349-3401

City Hall

401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421

www.bloomington.in.gov

EGRESS WINDOW MEASUREMENTS ARE AS FOLLOWS FOR UNITS 1 THROUGH 5

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 49 inches Width: 17 inches Sill Height: 23 inches Openable Area: 5.78 sq. ft.

Note: These measurements are for reference only. There is no violation of the

1-020-0

emergency egress requirements.

INTERIOR:

South Entry Hallway:

Repair the entry door to latch properly. PM-303.15

Unit 1 (1 Bedroom)

Living Room $20 \times 13 + 11 \times 8-6$:

Repair the entry door to latch properly. PM-303.15

Kitchen 12 x 7:

Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1

Replace the broken smoke detector. PM-704.1

Re-locate the smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

Bathroom:

Repair the door to latch properly. PM-304.6

Repair the broken cold water faucet to function as intended. PM-504.1

Bedroom 13-6 x 11:

Replace the old smoke detector. PM-704.1

Re-locate the smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. PM-704.1

UNIT 2 (EFF.)

Main Room 23 x 13-6:

Repair or replace existing smoke detector in a manner so that it functions as intended. PM-704.1

Kitchen:

Repair the faucet to eliminate the constant dripping. PM-504.1

Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1

Bathroom:

Repair the door to latch properly. PM-304.6

Repair the leaking hot water faucet handle on the sink to function as intended. PM-504.1

Repair the exhaust fan to function as intended, clanking fan. PM-603.1

Interior walls shall be free of holes, cracks, peeling paint and deteriorated drywall/plaster. PM-304.3

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials. PM-304.3

UNIT 3 (1 Bedroom)

Kitchen:

Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1

Repair the leaking sink faucet neck. PM-504.1

Bathroom:

Repair the door to fit the door jamb and to latch properly. PM-304.6

The water supply system shall be installed and maintained to provide a supply of water to plumbing fixtures, devices and appurtenances in sufficient volume and at pressures adequate to enable the fixtures to function properly, safely, and free from defects and leaks (repair faucet in a manner so that there is adequate water pressure and volume to the sink). PM-505.3

Bedroom 13-6 x 11:

Repair the door to fit the door jamb and to latch properly. PM-304.6

UNIT 4 (EFF.)

Living Room 23 x 13-6:

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials. PM-304.3

Kitchen:

Repair the stove burners to light as intended. PM-603.1

Bathroom:

Repair/replace the loud exhaust fan. PM-603.1

NORTH ENTRANCE

Entryway:

Repair the door to latch properly. PM-303.15

Lower Landing:

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and sagging materials, @ south end of hallway. PM-304.3

Stairway:

Secure the handrail so it is capable of withstanding normally imposed loads. PM-304.5 (interior)

UNIT 5 (1 Bedroom)

Living Room $20 \times 13 + 11 \times 8-6$:

Repair the entry door to latch properly. PM-303.15

Bathroom:

Repair the door to latch properly. PM-303.15

Seal edge of floor covering adjacent to bathtub. PM-304.1

Repair the cold water faucet on the sink, eliminate the constant dripping. PM-504.1

Replace the broken cold water faucet handle. PM-504.1

Bedroom 13-6 x 11:

Tighten the loose receptacle on the north wall and replace the missing cover plate. PM-605.1

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 37 inches Width: 16 inches Sill Height: 33 inches Openable Area: 4.11 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

UNIT 6 (EFF.)

Entry Hallway;

Repair the door to latch properly. PM-303.15

Bathroom:

Seal edge of floor covering adjacent to bathtub. PM-304.1

Secure the loose GFCI receptacle adjacent to the mirror. PM-605.1

Kitchen:

Properly ground the electrical receptacle @ sink. If the receptacle is on an ungrounded system, it is acceptable to install a 2-pole, ungrounded receptacle, or a GFCI receptacle. PM-605.1

Bedroom14 x 10:

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 37 inches Width: 16 inches Sill Height: 33 inches

Openable Area: 4.11 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

UNIT 7

Bedroom 11 x 10-10:

Existing Egress Window Measurements: Casement: Const. Yr. - 1925

Height: 37 inches Width: 20.5 inches Sill Height: 33 inches Openable Area: 5.26 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Kitchen:

Properly install or replace the aerator on sink faucet so that it functions as intended. PM-504.1

Repair the faucet sprayer on the sink to function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. PM-504.1

UNIT 8. NOTE: Finish turnover of unit, will check @ re-inspection.

Bedrooms:

Existing Egress Window Measurements: Slider: Const. Yr. - 1925

Height: 34.5 inches Width: 16 inches Sill Height: 43 inches

Openable Area: 3.83 sq. ft.

Note: These measurements are for reference only. There is no violation of the

40.10

emergency egress requirements.

Lower Level Hallway:

Water Heater Closet:

Re-attach the bi-fold doors to stay in the track, function as intended. PM-304.6

EXTERIOR:

Clean debris from the roof, gutters and downspouts. PM-303.7

Replace the missing and deteriorated (cracked and peeling) glazing compound on the windows. PM-303.13

Secure the loose conduit on the north side of structure. PM-605.1

Repair the deteriorated front porch steps. PM-302.3

OTHER REQUIREMENTS:

Required documentation:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.12.050 (d)

Boiler Room:

Boiler(s) are to be inspected every twelve months as per Indiana Code. A completed copy of the State of Indiana final Boiler Inspection report stating that the system is functioning as intended must be reviewed by this office before a Rental Occupancy Permit will be issued. PM-102.3, PM-504.1, & PM-603.1

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-100

Address:

1033 E. Maxwell Lane

Petitioner:

William Coulter

Inspector:

Jo Stong

Staff Report:

June 6, 2011: Conducted cycle inspection

June 8, 2011: Sent report

June 14, 2011: Received appeal

During a cycle inspection violations of the Property Maintenance Code were noted. The petitioner is seeking an extension of time until September 15, 2011 for completion of repairs. Petitioner states that the tenants will be moving out in mid-August, and that the property will then be vacant for a few months. He will service or replace the fire extinguisher before the original deadline of August 8, 2011.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the

possibility of fines.

Compliance Deadline:

August 8, 2011 to service or replace the fire extinguisher.

September 15, 2011 for all other violations.

Attachments:

Cycle report, appeal



prior to the meeting application deadline in order to be

placed on that months agenda!

Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

Petition Number:

Property Address	s: 1033 E. Maxwell	Lane	· ·	
Petitioner's Nam	e: William Coulte			
Address: 715 S. Pa	ark Ave.			
City: Bloomington)	State: Indiana	Zip Code: 47401	
Phone Number:	(812) 322-4994	E-mail Address: wico	ulte@gmail.com	
Owner's Name:	William Coulter			
Address: 715 S. Pa	irk Ave.			
City: Bloomington		State: Indiana Zip Code: 47401		
Phone Number:	812-322-4994	E-mail Address: wico	ulte@gmail.com	
Occupants: Ryan	Harvey, Allison Ko	walinski		
1. That the excepti health, safety, ar	ion is consistent nd general welfa	with the intent and purp re.	order for the Board to consider the request: cose of the housing code and promotes public the exception is to apply will not be adversely	
Identify the varia	ance type that y	ou are requesting fro	n the following drop down menu:	
Variance Type: A	An extension of tim	e to complete repairs. (Pet	ition Type: TV)	
Application or the	application will	ted with the Appeal not be considered to be n has to be submitted	(Will be assigned by BHQA)	

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.

E 9


- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

nature (Required):			
·			
·			
npleted by September 15th. I will so	ervice the fire extinguisher b	efore the original deadline.	
ing the work. The current lease exp e tenants and complicate the repair	process, I would like to be	gin the repairs in the latter	half of August, to be

important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form





Cycle Report

3711

OWNERS

COULTER, WILLIAM V. 715 S. PARK AVE. BLOOMINGTON, IN 47401

Prop. Location: 1033 E MAXWELL LN

Date Inspected: 06/06/2011

Inspectors: Jo Stong

Primary Heat Source: Gas

Property Zoning: RC

Number of Stories: 1

Number of Units/Structures: 1 / 1

Number of Bedrooms: 3

Max # of Occupants: 3

Foundation Type: Crawl Space

Attic Access: No

Accessory Structure: None

Monroe County Assessor's records indicate this structure was built in 1959. There were no requirements for emergency egress at the time of construction.

INTERIOR:

Living Room (16-2 x 13-7):

Repair and paint the crack in the ceiling at the entry to the hallway. PM-304.3

Hallway:

Clean the return air grille and change the filter if one is required. PM-603.1

Southwest Bedroom (11-6 x 10-1):

No violations noted.

Existing Egress Window Measurements (double-hung; both sashes removable):

Height: 37 inches Width: 26 ½ inches Sill Height: 43 inches Openable Area: 6.80 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

129

401 N. Morton Street Bloomington, IN 47404 Fax: (812) 349-3582 City Hall

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421 Housing Division: (812) 349-3401

Northwest Bedroom (13-5 x 11-5):

No violations noted.

Existing Egress Window Measurements (double-hung; both sashes removable):

Height: 37 inches Width: 34 ½ inches Sill Height: 43 inches Openable Area: 8.86 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

Bathroom:

No violations noted.

Northeast Bedroom (10-9 x 9-9):

No violations noted.

Note: Egress window measurements are the same as in the northwest bedroom.

Kitchen:

Service the metal-headed fire extinguisher, or replace it. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. PM-704.3

Laundry:

Properly secure the collar for the water heater flue pipe to the ceiling. PM-603.1

EXTERIOR:

Clean debris from the roof, gutters and downspouts. PM-303.7

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (this violation has a one-year deadline from the date of the cycle inspection)

Crawlspace:

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level: 0 parts per million (ppm)

Acceptable level in a living space: 9 ppm

Maximum concentration for flue products: 50 ppm PM-603.1

OTHER REQUIREMENTS:

Required documentation:

A completed copy of the Tenants & Owners Rights and Responsibilities Summary must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied.BMC16.12.050 (d).

Required documentation:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)

Thank you for your cooperation in the Residential Rental Occupancy Permit Program.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

13 July 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-096

Address:

1014 N. Jackson St.

Petitioner:

Adam Holden

Inspector:

Michael Arnold

Staff Report:

25 April 2011

Cycle Inspection

06 May 2011

Sent Report

15 June 2011

Received Appeal

During the cycle inspection it was noted that the Carpeting throughout the structure has been removed, leaving the sub-flooring exposed. The tenant removed the carpeting without the owner's consent and needs additional time to secure funding to purchase new carpeting.

Staff recommendation: Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline

stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the possibility of fines.

Compliance Deadline: 13 September 2011

Attachments: Inspection Report, Application



Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100

Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov



Property Address: /0/	4 N. JACK	SON BY:	
Petitioner's Name: Al	AM HOLDEN	,	
Address: 14970	HARTFORD K	?d	
City: Sunhuny	State: OH	Zip Code: 43074	
Phone Number: (6/4) 774	29//E-mail Address: A	HOLDEN SA @ GULAY, COM	7
Owner's Name: ADAn	Holden	,	
Address:			
City:	State:	Zip Code:	
Phone Number:	E-mail Address:		
Occupants:			
 That the exception is consisted health, safety, and general we 	ent with the intent and purp elfare.	order for the Board to consider the request: cose of the housing code and promotes public he exception is to apply will not be adversely	
Identify the variance type th	at you are requesting fron	n the following drop down menu:	M
Variance Type:			
Reminder: A \$20.00 filing fee must be sub- Application or the application of the application of the application of the meeting application of the meeting application.	will not be considered to be ation has to be submitted	(Will be assigned by BHQA)	
placed on that months agenda		Petition Number:	

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

"Complete THE INSTALLATION of New Kook Coverings."
1 • •
I would like to request A 30 day extension to
the existing chapering without my knowledge of
LOUISE & AMIN dOESN'T NAUR 1HE MONEY TO VEHING
Lharford RUR INSPECTION COROLINE SHE ASSORES
may that it can be ofcomplished with the
axtension of toma. THANK you.

Signature (Required):	1	
	1	

Name (Print): ADAM HOLDEN

Date:

6/10/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form

7618

OWNERS

=====

HOLDEN, ADAM W. AND DEBRA 13325 SANDOVER PLACE PICKERINGTON, OH 43147

AGENT

=====

HOLDEN, JOSHUA M. 631 N WALNUT BLOOMINGTON IN 47404

Prop. Location: 1014 N JACKSON ST

Date Inspected: 04/25/2011
Inspectors: Mike Arnold
Primary Heat Source: Gas
Property Zoning: RC

Number of Stories: 1

Number of Units/Structures: 1 / 1

Number of Bedrooms: 1
Max # of Occupants: 2
Foundation Type: Basement

Attic Access: No

Accessory Structure: shed

Interior:

Basement:

Provide operating power to smoke detector. PM-704.1

Main Level:

General:

Complete the installation of the new floor coverings. PM-304.3

Living Room (19-2 x 9-6), Back Porch Room:

Install approved closing device for storm door. PM-102.8 & PM-303.15

Kitchen $(13-2 \times 7-9)$:

All fire extinguishers must be inspected every 30 days and a record of that inspection shall be kept. Metal head extinguishers shall be subjected to maintenance at intervals of not more than one (1) year and shall have a tag or label securely attached that indicates the month and year the maintenance was performed as well as the identity of the person/company performing the service. Metal head extinguishers must be recharged every six years and hydro-tested every 12 years per NFPA-10. Plastic head extinguishers must be replaced every 12 years per NFPA-10. PM-704.3

Bedroom 11-3 \times 9-7):

Every window shall be capable of being easily opened and held in position by its own hardware. PM-303.13.2 (Measure openable area at reinspection).

Bathroom:

No violations noted

Exterior:

Main Structure:

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (This item has a deadline of 25 April 2012).

Repair the access cover to the basement. PM-303.16

Seal the cracks in the foundation walls. PM-303.5

Shed:

Repair the piers under the shed to be secure and structurally sound. PM-303.5

Required Documentation:

A completed copy of the Tenants & Owners Rights and Responsibilities Summary must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied.BMC16.12.050 (d).

A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC16.12.040

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

 $50~\mathrm{ppm}$

PM-603.1

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

July 13, 2011

Petition Type:

An extension of time to complete repairs

Petition Number:

11-TV-102

Address:

514 W. 6th St.

Petitioner:

Stasny & Horn IGP

Inspector:

Maria McCormick

Staff Report:

Cycle Inspection April 21, 2011

Application for Appeal received June 15, 2011

During the cycle inspection it was noted that there were several window sills that needed to be replaced. The exterior of the structure also needs to be scraped and painted. This building houses 4 apartments however only the 2 units on the lower level are currently occupied. The petitioned is asking for an extension of time until July 31, 2012 to complete the

replacement of the window sills and paint the structure.

Staff recommendation:

Grant the extension of time.

Conditions:

All repairs must be completed and re-inspected no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the


possibility of fines.

Compliance Deadline:

July 31, 2012

Attachments:

Application of Appeal; Cycle Report



BY:----



Page 1 of 2

Application For Appeal To The **Board of Housing Quality Appeals** P.O. Box 100 **Bloomington, IN 47402** 812-349-3420 hand@bloomington.in.gov

Property Address: 514 West Sixth	Street, Bloomington, IN 47404	
Petitioner's Name: Stasny & Horn	GP	
Address: 509 E Cottage Grove Ave S	te 1, PO Box 183	
City: Bloomington	State: Indiana	Zip Code: 47402
Phone Number: (812) 339-4676	E-mail Address: info@hp	oiu.com
Owner's Name: Stasny & Horn IGP		
Address: 509 E Cottage Grove Ave St	te 1, PO Box 183	1
City: Bloomington	State: Indiana	Zip Code: 47402
Phone Number: 812-339-4676	E-mail Address: info@hp	iu.com
Occupants: C Mitchel, Agent of Tena	ent; Z Swanson, Agent of Tena	nt
 That the exception is consistent the health, safety, and general welfar 	with the intent and purpose e.	ler for the Board to consider the request: e of the housing code and promotes public exception is to apply will not be adversely
Identify the variance type that y	ou are requesting from t	he following drop down menu:
Variance Type: An extension of tim	e to complete repairs. (Petitio	n Type: TV)
Reminder: A \$20.00 filing fee must be submitt Application or the application will a complete! A completed application prior to the meeting application de placed on that months agenda!	not be considered to be n has to be submitted	(Will be assigned by BHQA) //- TV - / UZ Petition Number:

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

Minor externation is limited to the propertion for exterior	or of this building is a rior peeling paint is of the two cellar tip in, ty and will be budget issues falls at the beg o schedule and compl	bserved on cas screened winde ed for complet jinning of the 2	ing and sills ows. These ion in caler 1012 paintin	of certain of t issues were no idar 2012. In th g season, we a	he forty window u t foreseen in the 2 nat the expiration re requesting an o	011 expense budget of a one year extens extension of time to J	age for ion uly
<u> </u>			35				

Signature (Required):

Name (Print): E Douglas Horn - General Partner - Stasny & Horn IGP

Date:

5/20/11

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



City of Bloomington Housing and Neighborhood Development

Cycle Report

2632

OWNERS

STASNY & HORN, IGP PO BOX 183 BLOOMINGTON, IN 47402-0183

Prop. Location: 514 W 6TH ST Date Inspected: 04/21/2011 Inspectors: Maria McCormick Primary Heat Source: Gas Property Zoning: RC

Number of Stories: 2

Number of Units/Structures: 4 / 1 Number of Bedrooms: 2 each Max # of Occupants: 2 each Foundation Type: Basement

Attic Access: No

Accessory Structure: None

The Monroe County Assessors records indicate that this structure was built in 1899. There were no minimum requirements for emergency egress at that time.

VARIANCE

01/20/1982 The Board of Housing Quality Appeals granted a variance to the basement access requirement.

INTERIOR:

Apt. #1 -

Living Room 14-0 x 17-0; Kitchen 3-7 x 9-5; Bathroom:

No violation noted.

Front Bedroom 11-0 x 9-5; Rear Bedroom 9-11 x 16-7:

No violation noted.

Existing Egress Window Measurements:

Height: 24 1/2 inches Width: 30 inches Sill Height: 30 inches Openable Area: 5.10 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

140

City Hall

Rental Inspections: (812) 349-3420 Neighborhood Division: (812) 349-3421

Housing Division: (812) 349-3401

Common Entry:

No violation noted.

Apt. #2-

Living Room 18-10 x 18-10; Kitchen/Dining Room 17-9 x 7-9; Bathroom:

No violation noted.

East Bedroom 10-0 x 13-0:

This room has a door to the exterior for egress purposes.

No violation noted.

North Bedroom 9-1 x 14-3:

No violation noted.

Existing Egress Window Measurements:

Height: 28 inches Width: 30 ½ inches Sill Height: 30 inches Openable Area: 5.83 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Apt. #3 & 4-

These two units are under construction and are not habitable at the time of inspection. Both units must be completed and inspected prior to occupancy.

Basement -

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

PM-603.1

EXTERIOR:

Scrape and paint exterior surfaces where paint is peeling or wood is exposed. PM-303.2 (This item only has a compliance deadline of April 21, 2012.)

Replace all missing and/or deteriorated (cracked and peeling) glazing compound on the windows. PM-303.13

Remove all the trees growing along the foundation on the north side of the building. PM-302.4.1

Properly repair or replace all the damaged and deteriorated wooden window sills. PM-303.13

OTHER REQUIREMENTS:

Complete the enclosed registration form. A street address is required for both owner and agent. This form must be signed by the owner. BMC16.12.060

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.12.080 (b): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.12.080 (b)